

CLSE  
AP

Submit 3 Copies To Appropriate District

Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87420

District IV

1220 S. St. Francis Dr. Santa Fe, NM 87505

State of New Mexico

Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.

30-015-23658

5. Indicate Type of Lease

STATE ☐ FEE ☐

6. State Oil &amp; Gas Lease No.

7. Lease Name or Unit Agreement

Name:

Red Lake Unit

8. Well No. 24

9. Pool name or Wildcat

Red Lake, East

STANDARD NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other ☐

2. Name of Operator

Beach Exploration, Inc.

3. Address of Operator

800 North Marienfeld Ste. 200

4. Well Location

Unit Letter G : 1986 feet from the North line and 1983 feet from the East line

Section 36

Township 16S

Range 29E

NMPM

County Eddy

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

3697 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☒ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐CASING TEST AND CEMENT JOB ☐OTHER: Re-Classify to TA Status ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

RLU #24 TA Procedure

1 POOH w/tubing

2 RU Wireline, RIH w/gauge ring, POOH

3 RIH w/ML set CIBP, set at 1730', POOH

4 RIH w/bailer and dump 35' cmt on CIBP

5 Load hole and conduct MIT w/OCD and file for TA'd Status

500# - 30 min w/chart

Notify OCD 24 hrs. prior to any work done

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Engineering

DATE

Type or print name Lizbeth Lodle

(This space for State use)

Telephone No. 915-683-6226

APPROVED BY

TITLE

DATE

FEB 18 2002

Conditions of approval, if any: