

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED BY
MAR 22 1984
O. C. D.
ARTESIA, OFFICE

54. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation ✓	8. Farm or Lease Name Havins "QK"
3. Address of Operator 207 South 4th St., Artesia, NM 88210	9. Well No. 1
4. Location of Well UNIT LETTER J 2170 FEET FROM THE South LINE AND 1650 FEET FROM THE East LINE, SECTION 30 TOWNSHIP 16S RANGE 26E NMPM.	10. Field and Pool, or Wildcat Undes. San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 3403' GR	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 110S.

3-15-84. Plugged well as follows: Pulled rods, swab well down, lay down tubing. Filled 4-1/2" casing from bottom to top with 6 yards 5-sx ready-mix. Set dry hole marker. Surface will be restored.

Post FD-2
3-30-84
P+H

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>Luana G. Doolittle</i></u>	TITLE <u>Production Supervisor</u>	DATE <u>3-20-84</u>
APPROVED BY <u><i>Darryl Brooks</i></u>	TITLE <u><i>Geologist</i></u>	DATE <u>6-4-84</u>
CONDITIONS OF APPROVAL IF ANY:		