

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

NM OIL CONS. COMMISSION  
SUBMIT IN THE  
Drawings and Instructions  
on reverse side  
Artesia, NM 88210

Form approved.  
Budget Bureau No. 42-R444

SF/John

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	JUN 15 1982	5. LEASE DESIGNATION AND SERIAL NO. NM 0557370
2. NAME OF OPERATOR Marbob Energy Corporation	O. C. D.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Drawer 217, Artesia, N.M. 88210	ARTESIA, OFFICE	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below) At surface 330 FSL & 330 FEL		8. FARM OR LEASE NAME ARCO Federal
		9. WELL NO. 1
		10. FIELD AND POOL, OR WELLS AT Red Lake (Q-G-SA) Ext.
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 27-17S-27E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3511' GR	12. COUNTY OR PARISH Eddy
		13. STATE N.M.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	PULL OR ALTER CASING
CRACKURE TREAT	MULTIPLE COMPLETE
SHOOT OR ACIDIZE	ABANDON*
REPAIR WELL	CHANGE PLANS
(Other)	


SUBSEQUENT REPORT OF:

WATER SHUT-OFF	REPAIRING WELL
CRACKURE TREATMENT	ALTERING CASING
SHOOTING OR ACIDIZING	ABANDONMENT*
(Other)	Plug & abandon X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

12/21/81 We plugged this well by running cement from TD to 950', let cement set for 3 hrs., tagged cement @ 950', set a 25 sack plug from 100' to 350', and a 10 sack plug @ surface. A dry hole marker was set. Location has been cleaned, pits covered, deadmen removed. Tanks still remain on location. Will notify when these have been removed.



OIL & GAS  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *Carolyn Jones* TITLE Production Clerk

DATE 1/8/82

(This space for Federal use only)

APPROVED BY (Off. Sgd.) PETER W. CHESTER  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

JUN 11 1982

FOR

JAMES A. GILLHAM \*See Instructions on Reverse Side  
DISTRICT SUPERVISOR