

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2080  
SANTA FE, NEW MEXICO 87501

OCT - 7 1981

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fed <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LC-3650	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P X A		7. Unit Agreement Name
Name of Operator Amoco Production Company		8. Farm or Lease Name State CD Gas Com.
Address of Operator P. O. Box 68, Hobbs, NM 88240		9. Well No. 1
Location of Well UNIT LETTER G, 1880 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 11 TOWNSHIP 17-S RANGE 27-E NMPM.		10. Field and Pool, or Wildcat Wildcat Morrow
15. Elevation (Show whether DF, RT, GR, etc.) 3438.9' GL		12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

P X A well by the following method:

Spotted 100' plugs with 45 sacks of Class H cement at the following intervals:  
9100-9200, 8400-8500, 7400-7500, 6300-6400', 5180-5280', 2960-3060,  
1950-2050, and 350-450'.

Spotted 15 sack surface plug and erected abandonment marker. Will notify when location is ready for inspection.

0+4-NMOCD, A 1-Hou 1-Susp 1-W. Stafford, Hou 1-MDR 1-Tenneco, SA  
1-Conoco, Hobbs

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mark Randolph TITLE Assist. Admin. Analyst DATE 10-2-81

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: