

c/5f

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐
2. NAME OF OPERATOR
Forister & Sweatt
3. ADDRESS OF OPERATOR
PO Box 161, Artesia, NM 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660 FNL 2130 FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☒
☒
☐
☐
☐
☐
☐
☐

RECEIVED

DEC 28 1982

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OIL & GAS
MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Perforated Lovington sand-2517-2530 14½ holes. Treated w/500 gals 15% acid. Frac w/15,000 gal 40# gelled KCL water w/ 8400# sand.
2. Perforated Premier-2406-2422 17½ holes. Treated w/ 700 gals 15% acid. Frac w/ 20,000 gal 30# gelled KCL water w/ 24,700# sand.
3. Perforated Metex-2266-2270 5½ holes and 2280-2284 5½ holes. Treated with 500 gal. Frac w/ 15,000 gal 30# KCL water w/ 17,400# sand.
4. Perforated Penrose-1840-1850 11½ holes and 1904-1914 11½ holes, 1946-1950 5½ holes, 1956-1960 5½ holes. Treated w/ 1000 gal 15% acid. Frac w/ 40,000 gal 30# gelled KCL water w/ 49,500# sand.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Charles F. Smith TITLE Director DATE 12-27-82

ACCEPTED FOR RECORD

(This space for Federal or State office use)

(ORIG. SGD.) DAVID R. GLASS

APPROVED BY _____ DATE _____
CONDITIONS OF APPROVAL IF ANY _____

JAN 14 1983

MINERALS MANAGEMENT SERVICE
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

5. LEASE
NM 15007
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
RECEIVED
8. FARM OR LEASE NAME
Bear Draw Red **JAN 18 1983**
9. WELL NO.
4 **O. C. D.**
10. FIELD OR WILDCAT NAME ARTESIA, OFFICE
Bear Draw Q.G.SA.
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec 28 T16S R29E
12. COUNTY OR PARISH Eddy 13. STATE New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3634.8 GL