

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NM OIL CONS. COMMISSION
Dr. SUBMIT IN TR. CATE*
Other instructions on re-
verse side
Artesia, NM 88210

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM 17216	
2. NAME OF OPERATOR BRUCE ANDERSON		6. IF INDIAN, ALLOTTEE OR TRIBE NAME -----	
3. ADDRESS OF OPERATOR 900 Allied Bank Plaza, 1000 Louisanna St., Houston, TX		7. UNIT AGREEMENT NAME -----	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL, 660' FEL, SE $\frac{1}{4}$ NE $\frac{1}{4}$, Unit H		8. FARM OR LEASE NAME Peterson Federal	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3513 G.L.		10. FIELD AND POOL, OR WILDCAT Wildcat	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 22, 16S, 27E	
		12. COUNTY OR PARISH Eddy	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1-11-83 Total Depth 2350 feet, dolomite. small gas show in Premier sand at 1422-33. Non commercial.

Propose to plug and abandon as follows:

1. Spot 100 foot plug 1400 to 1500 feet (across Premier)
2. Pull 7" casing set @ 1060 feet.
3. Spot 100 foot plug @ 650 to 750 feet.
4. Spot 100 foot plug @ 300 to 400 feet (8-5/8" csg. @ 350')
5. 15 sx. plug at surface.

Work to commence on approval.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Operator's Agent

DATE 1-11-83

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF

(ORIG. SGD) DAVID R. GLASS

DATE

JAN 11 1983
JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side