

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		6. LEASE DESIGNATION AND SERIAL NO. NM-18226	
2. NAME OF OPERATOR Read & Stevens, Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 1518, Roswell, NM 88202		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 4620' FSL & 990' FWL		8. FARM OR LEASE NAME Lyle Federal	
14. PERMIT NO.		9. WELL NO. 2	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3794.3 GR		10. FIELD AND POOL, OR WILDCAT Wildcat San Andres	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 5-16S-30E	
		12. COUNTY OR PARISH Eddy	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

140' in
Notify BLM 24 hrs prior to P & A.
Set 400' cmt plug above perfs 2253'-2341'.
Set 100' plug @ top of salt @ 1,190'.
Set 100' plug @ shoe of surf pipe, 505'.
Set 50' surf plug and install dry hole marker.
All plugs tagged w/tbg, and all fluid will be mud laden.

RECEIVED

MAY 8 10 23 AM '90

CARLOS
AREA

per phone conversation
w/ Shannon Shaw of the
BLM this date, we have
verbal approval to P&A

Jan
5-2-90

SJS

18. I hereby certify that the foregoing is true and correct

SIGNED

John C. Mader Jr.

TITLE Petroleum Engineer

DATE 4/30/90

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

5 24 90

CONDITIONS OF APPROVAL, IF ANY: