Form 3160-5								
(August 1999)	UNITED STAT DEPARTMENT OF TH	E INTERIOR	N.M. (Oil Cons		FOI OMI Expires	RM APPROVED B No. 1004-0135 1 November 30, 200	0
	BUREAU OF LAND MA	NAGEMENT	811 5	. 1st Str		Serial N	io.	
SUND	Y NOTICES AND REP	PORTS ON W	ELLARTOS	ia, NM 8	8210-40		015 58 otlee or Tribe Nat	
abandoned w	AY NOTICES AND REA his form for proposals ell. Use Form 3160-3 (A	PD) for such p	proposals.		0. It Indi	18 <u>1</u> , A10		
SUBMIT IN TI	IPLICATE - Other Ins	tructions on	reverse sid	le .	7. lf Uni		Agreement, Nan	e and/or No.
1. Type of Well					8. Well 1	Name an	nd No.	
Z. Name of Operator	Other		<u> </u>				d Fed. 1	4
Hanson Energy					9. APIW			
3a. Address			No. (include are				15-25139 I. or Exploratory	Area
R 342 S Haldema 4. Location of Well (Footage, Sec			/48-2134	1			T-SR	
	Sec. 35 T17S		М		11. Count	y or Pari	ish, State	
					Ed	ldy,	NM	
					PEPORT C		HER DATA	
	PROPRIATE BOX(ES)	10 INDICA II			, KEPORT, O			
TYPE OF SUBMISSION				OF ACTION				<u> </u>
	Acidize	Deepen	_	Production (S	itari/Resume)	_	Water Shut-Off Well Integrity	
Notice of Intent	Alter Casing	Fracture T		Reclamation Recomplete			Other	
😡 Subsequent Report	 Casing Repair Change Plans 	Plug and A	_	Temporarily	Abandon	-		
 Final Abandonment Notice 13. Describe Proposed of Complete If the proposal is to deeped dire Attach the Bond under which it 	ctionally of recomplete honzon	Plug Back entiment details, inc stally, give subsurf	uding estimated ace locations an	Water Dispose d starting date of d measured and BI M/BIA. Rec	f any proposed w true vertical dep nuired subsequer	nt report	ts shall be filed	vithin 30 days
13. Describe Proposed or Complete If the proposal is to deeped dire Attach the Bond under which it following completion of the inv testing has been completed. Fi determined that the site is ready Made repair Will resume ACCEF (ORIG	d Operation (clearly state all pe clionally or recomplete horizon ne work will be performed or p olved operations. If the operation al Abandonment Notices shall for final inspection.) s, pumped Well production whe TED FOR RECORD SGD.) DAVID R. G JAN 3 1 2001	Plug Back ertinent details, inc itally, give subsurf provide the Bond h ion results in a mu be filed only after to Test en new Ta	Tank. E ank Batt Rank Batt Rece locations an No. on file with hillple completion or all requirement Tank. E ank Batt REC OCD - A	Water Dispose d starting date of d measured and BLM/BIA. Ree n or recompletion ints, locivity re	f any proposed w true vertical dej quired subseque: on in a new inter celamation, have	nt report rval, a P been co	ts shall be filed w	vithin 30 days be filed once
13. Describe Proposed or Complete If the proposal is to deepen dire Attach the Bond under which to following completion of the inv testing has been completed. Fit determined that the site is ready Made repair Will resume ACCEF (ORIG	d Operation (clearly state all pe clionally or recomplete horizon ne work will be performed or p olved operations. If the operation al Abandonment Notices shall for final inspection.) s, pumped Well production whe TED FOR RECORD SGD.) DAVID R. G JAN 3 1 2001	Plug Back ertinent details, inc itally, give subsurf provide the Bond h ion results in a mu be filed only after to Test en new Ta	Tank. E ank Batt Rank Batt Rece locations an No. on file with hillple completion or all requirement Tank. E ank Batt REC OCD - A	Water Dispose d starting date of d measured and BLM/BLA. Red n or recompletion nor recomple	f any proposed w true vertical deg quired subsequer on in a new inter clamation, have 2 BBls finishe	d	2001 JAN 25 - A F	vithin 30 days be filed once e operator has
 13. Describe Proposed or Complete If the proposal is to deepen dire Attach the Bond under which it following completion of the invite testing has been completed. Fi determined that the site is ready Made repair Will resume ACCEF (ORIG) 14. I hereby certify that the foregoin Name (Printed/Typed) 	d Operation (clearly state all pe clionally or recomplete horizon ne work will be performed or p olved operations. If the operation al Abandonment Notices shall for final inspection.) s, pumped Well production whe TED FOR RECORD SGD.) DAVID R. G JAN 3 1 2001	Plug Back ertinent details, inc itally, give subsurf provide the Bond h ion results in a mu be filed only after to Test en new Ta	Tank. E ank Batt Rank Batt Rece locations an No. on file with hillple completion or all requirement Tank. E ank Batt REC OCD - A	Water Dispose d starting date of d measured and BLM/BIA. Ree n or recompletion nor recompletion not, iocluding re Produced ery is FOUCED RTESIA BLU 91 51 4 811	f any proposed w true vertical deg quired subsequer on in a new inter clamation, have 2 BBls finishe	d	is shall be filed form 3160-4 shall ompleted, and the 2001 JAN 25 - A 7 45	within 30 days be filed once e operator has
 13. Describe Proposed or Complete If the proposal is to deepen dire Attach the Bond under which it following completion of the invite testing has been completed. Fi determined that the site is ready Made repair Will resume ACCEF (ORIG) 14. I hereby certify that the foregoin Name (Printed/Typed) 	d Operation (clearly state all pe clionally or recomplete horizon ne work will be performed or p olved operations. If the operation al Abandonment Notices shall for final inspection.) s, pumped Well production who TED FOR RECORD SGD.) DAVID R. G JAN 3 2001	Plug Back ertinent details, inc itally, give subsurf provide the Bond N ion results in a mu be filed only after to Test en new Ta	Tank . H ank Batt George Start Tank . H ank Batt <i>George Start</i> <i>Color A</i> <i>Color A</i> <i>C</i>	Water Dispose d starting date of d measured and BLM/BIA. Ree n or recompletion nor recompletion nor recompletion roduced ery is FOUCED RTESIA BLLU91	f any proposed w true vertical deg quired subseque: on in a pew inter- clamation, have finishe Bulloch ontact	d	e. Artes	within 30 days be filed once e operator has
 13. Describe Proposed or Complete If the proposal is to deeped dire Attach the Bond under which it following completion of the invite testing has been completed. Fi determined that the site is ready Made repair Will resume ACCEF (OFIG) 14. I hereby certify that the foregoin Name (Printed/Typed) 	d Operation (clearly state all pe clionally or recomplete horizon ne work will be performed or p olved operations. If the operation al Abandonment Notices shall for final inspection.) s, pumped Well production who TED FOR RECORD SGD.) DAVID R. G JAN 3 2001	Plug Back ertinent details, inc itally, give subsurf provide the Bond h ion results in a mu be filed only after to Test en new Ta	Tank . H ank Batt George Start Tank . H ank Batt <i>George Start</i> <i>Color A</i> <i>Color A</i> <i>C</i>	Water Dispose d starting date of d measured and BLM/BIA. Ree n or recompletion nor recompletion nor recompletion roduced ery is FOUCED RTESIA BLLU91	f any proposed w true vertical deg quired subseque: on in a pew inter- clamation, have finishe Bulloch ontact	d	e. Artes	within 30 days be filed once e operator has
 13. Describe Proposed of Complete If the proposal is to deeped dire Attach the Bond under which it following completion of the invite testing has been completed. Fi determined that the site is ready Made repair Will resume Made repair Will resume ACCEF (ORIG) 14. I hereby certify that the foregoin Name (Printed/Typed) D Signature 	d Operation (clearly state all pe clionally or recomplete horizon ne work will be performed or p olved operations. If the operation al Abandonment Notices shall for final inspection.) s, pumped Well production who TED FOR RECORD SGD.) DAVID R. G JAN 3 2001	Plug Back ertinent details, inc itally, give subsurf provide the Bond N ion results in a mu be filed only after to Test en new Ta	Tank. E ank Batt Alughing estimated ace locations an No. on file with alliple completion of all requirement Tank. E ank Batt OCD A COCD	Water Dispose d starting date of d measured and BLM/BIA. Ree n or recompletion nor recompletion nor recompletion roduced ery is FOUCED RTESIA BLLU91	f any proposed w true vertical deg quired subseque: on in a new inter- clamation, have 2 BBls finishe Bulloch ontact 00	d	e. Artes	within 30 days be filed once e operator has
 13. Describe Proposed of Complete If the proposal is to deeped dire Attach the Bond under which it following completion of the invite testing has been completed. Fi determined that the site is ready Made repair Will resume Made repair Made repair Will resume 	d Operation (clearly state all pe clionally or recomplete horizon ne work will be performed or p olved operations. If the operation al Abandonment Notices shall for final inspection.) s, pumped Well production who TED FOR RECORD SGD.) DAVID R. G JAN 3 2001	Plug Back ertinent details, inclusily, give subsurf provide the Bond N ion results in a mu be filed only after to Test en new Ta ASS	Tank . E ank Batt Grant Batt Fille Completion Frank Batt Content Free Content Title Age Date	Water Dispose d starting date of d measured and BLM/BIA. Ree n or recompletion nor recompletion nor recompletion roduced ery is FOUCED RTESIA BLLU91	f any proposed w true vertical deg quired subseque: on in a new inter- clamation, have 2 BBls finishe Bulloch ontact 00	d . k Av Pers	e. Artes	within 30 days be filed once e operator has

.