Form 3160-5 11. FD STATE	S) SUBMIT IN TRLATE	
Form 3160-5 (November 1983) (Formerly 9-331) DEPARTMENT OF THE INTERIOR Ferrer side) BUREAU OF LAND MANAGEMENTIA, NM 88210		5. LEASE DESIGNATION AND SERIAL NO. NM 38475
		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REP	or plug back to a different reservation.	
Use "APPLICATION FOR PERMIT—"	RECEIVED BY	
1. OIL (V) GAB	11000	7. UNIT AGREEMENT NAME
WELL WELL OTHER	AUG 15 1985	8. FARM OR LEASE NAME
2. NAME OF OPERATOR Yates Petroleum Corporation		Hedgehog ABM Federal
3. ADDRESS OF OPERATOR	O, C. D.	9. WBLL NO.
207 South 4th St., Artesia, NM 8821		1
1. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)		10. FIELD AND POOL, OR WILDCAT Und.
At surface		Square Lake Grayburg SA
1650 FSL & 2310 FEL, Sec. 26-T16S-R31E		SURVEY OR AREA
		Unit J, Sec. 26-16S-31E
14. PERMIT NO. 15. ELEVATIONS (Show	whether DF, BT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
4131.5'	GR.	Eddy NM
18. Check Appropriate Box To Ir	disasa Natura of Notice Report or	Other Data
Check , tpp.ophate 22.		
NOTICE OF INTENTION TO:	3030	
TEST WATER SHUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
PRACTURE TREAT MULTIPLE COMPLETE	FRACTUBE TREATMENT SHOOTING OR ACIDIZING	ALTERING CASING ABANDONMENT®
SHOOT OR ACIDIZE X ABANDON® REPAIR WELL CHANGE PLANS	(Other)	
(Other) Perforate, Treat	(Norm: Report result	ts of multiple completion on Well pletion Report and Log form.)
Propose to set CIBP at 3900' w/ceme Perforate Premier at 3755-3793' w/l 15% Spearhead acid.	nt on top (35)	
Will swab back load and evaluate.		
		Š
18. I hereby certify that the foregoing is true and correct six and another and another Ti	TLE Production Supervisor	DATE 8-1-85
(This space for Federal or State office use)		8-1485
APPROVED BYTI	TLE:	DATE