

RECEIVED BY

NM OIL CONS. COMMISSION

Drawer DD

Artesia, NM 88210

UNITED STATES DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYForm approved:  
Budget Bureau No. 42-R1424.  
5. LEASE DESIGNATION AND SERIAL NO.

FEB 01 1986

O. C. D.

ARTESIA, NM

NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

NM-10276

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

TXO Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Und. High Lonesome Queen

11. SEC., T., R., W., OR BLK. AND  
SURVEY OR AREA

Sec. 8-T16S-R29E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3661' G.L.

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

ABANDON OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

ABANDONING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

01/08/86: Perf 1718-1756' w/13 holes. Acidized w/1,000 gals 10% NE acid and balls.  
Fraced w/20,000 gals gel water, 18,500 lbs 20-40 and 25,000 lbs 10-20 sand.

01/10/86-

01/12/86: Swabbed dry. No show of oil or gas.

01/16/86: Set CIBP at 1705' w/30' of cement. Perfed 1661-1669' w/10 holes.  
Acidized w/1,000 gals 10% NE acid. Swabbed dry.~~From Baker Chapter (1-21-86)~~~~Propose to plug and abandon by~~~~Set 25 cement plug from 1570 to 1660' inside 5 1/2" casing and log~~~~Set 25 cement plug from 600 to 700'~~~~Set 25 cement plug from 170 to 270' across 9 5/8" casing inside 5 1/2" casing~~~~Set 50 cement plug down headhead to cover 9 5/8" casing~~~~Set 10 cement plug~~~~Install dry hole marker~~

ACCEPTED FOR RECORD

GWD

JAN 31 1986

18. I hereby certify that the foregoing is true and correct

SIGNED

Paul Regisale

TITLE

CARLSBAD, NEW MEXICO  
OPERATIONS MANAGER

DATE Jan. 21, 1986

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side