

BUREAU OF LAND MANAGEMENT

Artesia, NM 88210

SONDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

SunTex Resources, Inc.

3. ADDRESS OF OPERATOR

8111 LBJ Freeway, Suite 570, Dallas, Texas

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1650 FNL & 1650 FWL, Sec. 20, T16S, R29E, NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3652 3637.3 GL

5. LEASE DESIGNATION AND SERIAL NO.

LC-046199A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

N/A

7. UNIT AGREEMENT NAME

N/A

8. FARM OR LEASE NAME

Ginger Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

High Lonesome-Q

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 20, T16S, R29E

12. COUNTY OR PARISH

Eddy

13. STATE

NM.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☒SHOOT OR ACIDIZE ☒REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANE ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

- 1) MIRU well service unit.
- 2) Install BOP & test to 4000 psig.
- 3) Test casing to 3500 psig.
- 4) Run gamma ray - cement bond log from PBTD-top of cement.
- 5) Perforate 1790-1802 with 1 hpf.
- 6) TIH with tubing & acidize with 1000 gallons 10% NEFE.
- 7) Frac with 18000 gallons cross link gel with 21000# 20/40 and 17000# 12/20 sand.
- 8) Flow well back.
- 9) Place on pump, if necessary

RECEIVED BY

JAN 24 1986

O. C. D.

ARTESIA, OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

James M. Salter

TITLE

Operations Manager

DATE

1/9/86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

1-23-86

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side