

C/SF

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to the same reservoir. Use Form 9-331-C for such proposals.)

1. oil well  gas well  other

2. NAME OF OPERATOR  
Sun-Tex Resources, Inc

3. ADDRESS OF OPERATOR  
12160 Abrams Rd. Suite 47, Dallas, TX. 75243

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1650 TNL & FWL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

RECEIVED BY  
MAR 27 1987  
O. C. D.  
ARTESIA, OFFICE

5. LEASE  
LC-046119 A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
N/A

7. UNIT AGREEMENT NAME  
N/A

8. FARM OR LEASE NAME  
Ginger Federal

9. WELL NO.  
#1

10. FIELD OR WILDCAT NAME  
High Lonesome - Q

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 20, T16S, R29E

12. COUNTY OR PARISH  
Eddy

13. STATE  
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3637.3

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>		<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>		<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>		<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>		<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>		<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>		<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>		<input checked="" type="checkbox"/>
(other)			

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Spotted 25 sks. of cement @ 1800'. Tagged plug @ 1463'.
2. Spotted 25 sks. of cement @ 350' @ 8 5/8 shoe.
3. Spotted 4 sks. of cement @ surface & set up P & A Marker.

ACCEPTED FOR RECORD

MAR 25 1987

CARLSBAD, NEW MEXICO

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct Raymond M. Malferada

SIGNED \_\_\_\_\_ TITLE P & A Supervisor DATE 3-12-87

(Orig. Sgd. Must be in this space) (This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE 3-25-87  
CONDITIONS OF APPROVAL, IF ANY:

Approved for release by the well bore.  
Lateral operations are not to be conducted until  
surface restoration is completed.

\*See Instructions on Reverse Side

Post ID-2  
4-3-87  
PFA