(November 1983) (Formerly 9–331)  UNITED STATES DEPARTMEN OF THE INTER BUREAU OF LAND MANAGEMEN  SUNDRY NOTICES AND REPORTS  (Do not use this form for proposals to drill or to deepen or plus	Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO LC-062996 B 6 IF INDIAN, ALLOTTEE OR TRIBE NAME				
Use "APPLICATION FOR PERMIT—" for such  OIL WELL X WELL OTHER  2. NAME OF OPERATOR  SunTex Resources, Inc.  3. ADDRESS 10 160 TOR  12160 Abrams Road Suite 417 Dal  4. LOCATION OF WELL (Report location clearly and in accordance with an See also space 17 below.)  At surface	FEB 19 1987  Cex Resources, Inc.  O. C. D.  O Abrams Road Suite 417 Dallas, TX, 75243				
14. PERMIT NO. 15. ELEVATIONS (Show whether a 3655.5	DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE Eddy NM			
Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  TEST WATER SHUT-OFF PULL OR ALTER CASING SHOOT OR ACIDIZE REPAIR WELL (Other)  (Other)  (Other)  (Other)  (Other)  (Other)  (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)  17. Describe the describe of completion of Report and Log form.)  18. Describe the describe of completion of Report and Log form.)  Procedure to plug well. Cement was circulated to surface on both surface casing and production casing.					
<ol> <li>Set cast-iron bridge plug at 1725' (31' above upper perf). Spot 35' cement on top of plug.</li> <li>Set 100' cement across surface casing shoe (305') from</li> </ol>					
250' to 350'.  3) Set 50' surface plug.					
		·			

\*Please respond as soon as possible. Call 214-437-1212. Thank you.

8. 1	bereby coultry that the foregoing is true and correct			
5	NGNED	TITLE	DATE	
·- (	This space for Egderel or State office use)			
	APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE	2.178/

Post FD-2 2-22-87 P&A

\*See Instructions on Reverse Side