State of New Mexico Form C-133 Submit 3 Co Energy, Minerals and Natural Resources Department Revised 1-1-89 to Appropriate District Office OIL CONSERVATION DIVISION DISTRICT WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 30-015-30240 Santa Fe, New Mexico 87504-2088 DISTRICT 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 82210 STATE X FEE DISTRICT III
1000 Rio Benzos Rd., Aziec, NM 87410 6. State Oil & Gas Lease No. NA 1527 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) OXY Wallace State Type of Well: WELL X WET [23248 OTHER 8. Well No. Name of Ope 16696 OXY USA Inc. 9. Pool name or Wildcat Address of Operator Draw Morrow P.O. Box 50250 Midland, TX 79710-0250 Well Location North 650 Feet From The Feet From The BHL County hip 175 Range 275

10. Elevation (Show whether DF, RKB, RT, GR, etc.) **NMPM** Section Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ALTERING CASING PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDONMENT CHANGE PLANS COMMENCE DRILLING OPNS. TEMPORARILY ABANDON CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** OTHER: Plusback & Sidetrack OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See Other Side



I hereby certify that the informature TYPE OR FRONT NAME	David Stewart	Regulatory Analyst	DATE 9(15/98 TELEPHONE NO. 915685571
(This space for State Use) AFTROVED BY CONDITIONS OF AFTROVAL	ORIGINAL SIGNED BY TIM W. GUM DISTRICT II SUPERVISOR	Ε	9-16-98

DRILL 7-7/8" HOLE TO 9184 8/9/98, CIRC HOLE. RIH W/ OH & FMI LOGS, POOH W/O EVALUATION. NOTIFIED NMOCD, RECEIVED VERBAL APPROVAL FROM TIM GUM TO SPOT THE FOLLOWING PLUGS. RIH OPEN ENDED TO 9184', SPOT 50sx CL H CMT PLUG FROM 9184-9035'. POOH TO 8811', SPOT 33sx CL H CMT PLUG FROM 8811-8711'. POOH TO 7900', SPOT 33sx CL H CMT PLUG FROM 8000-7900'. POOH TO 7900', SPOT 225sx CL H CMT W/.9% CD31 PLUG FROM 7900-7400', POOH, WOC. CIRC HOLE. RIH & TAG CEMENT @ 7472', DRILL OUT TO 7775', RUN MULTI SHOT GYRO LOG, POOH. RIH W/ DIRECTIONAL TOOLS, ORIENT TOOL FACE, TIME DRILL FROM 7748-7760', SAMPLES FROM 7757-7759' INDICATE 95% FORMATION. DRILL AHEAD. DRILL TO TD @ 9150' 8/21/98, POOH, CIRC HOLE, SPOT NUT PLUG PILL ON BOTTOM. RIH & LOG, POOH. RIH W/ 4-1/2" 11.6# CSG & SET @ 9149'. M&P 350sx SUPER C MODIFIED W/.5% FL-52 + .5% FL-25 + 8#/sx GILSONITE FOLLOWED BY 75sx Cl C W/.1% FL-25, DISP W/ FW, PLUG DOWN @ 0730hrs MDT 8/23/98. CEMENT DID NOT CIRCULATE, WOC. NMOCD WAS NOTIFIED BUT DID NOT WITNESS. ND BOP, SET SLIPS & CUT CSG. JET & CLEAN PITS, RELEASE RIG @ 1500hrs MDT 8/23/98. SI WOCU.