

27. Acid, Shot, Fracture, Cement, Squeeze, Etc.
Washington 33 State #12 – San Andres
30-015-30348

Perf 5-1/2" csg 2928-2372', 52 shots, select fire. PPI acidize Sa 2372-2928' w/2 bbls 15% HCL acid per setting. Frac 2372-2928' w/8000 gals 25# viking gel & 35,000 gals 10# linear gel carrying 90,000# 20/40 brady sand followed by 10,000 gals 10# linear gel carrying 30,000# 20/40 resin coated sand. Flush w/2380 gals 10# Linear gel.

Perf 5-1/2" csg 1449-2107', 25 holes. PPI 1449-2107' w/2 bbls 15% HCL per setting. Frac 1449-2107' w/8000 gals 25# viking gel followed by 36,000 gals 10# linear gell carrying 85,000# 20/40 brady sand & 7000 gals 10# linear gell carrying 22,000# 20/40 resin coated sand, flush w/1500 gals 10# linear gell.