SUNDR Do not use th abandoned we	UNITED STATES DEPARTMENT OF THE IN BUREAU OF LAND MANAGI Y NOTICES AND REPOR is form for proposals to dr bil. Use Form-3160-3 (APD) IPLICATE - Other instruct	TERIOR EMENT 811 TS ON WELLS III or to re-enter a for such proposals	n 	Division FORM APPROVE OMB No 1004-01 Expires July 31: 19 10-2834 Senal Nu NM 02-55 2 16 If Indian, Allottee or Tribe 1 If Unit or CA/Agreement, N	27 Name	
Type of Weli				-		
Oil Well X Gas Well J Other				8. Well Name and No.	(+f (
2. Name of Operator OXY USA INC. 16696				9. API Well No.		
3a. Address P.O. BOX 50250 3b. Phone No. (include area code)				30-015-30386		
MIDLAND, TX 79710-0250 915-685-5717 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				10. Field and Pool. or Exploratory Area Undes. Logan Draw Morrow		
660 FNL 1650 FEL NWNE (B) Sec 23 TITS RZTE				11. County or Parish, State EDDY NM		
12 CHECK A	PROPRIATE BOX(ES) TO	INDICATE NATU	E OF NOTICE		`A	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, R TYPE OF SUBMISSION TYPE OF ACTION					A	
Nouce of Intent	Acidize	Deepen Fracture Treat	Reciamation	Well Integrat		
Subsequent Report	- ¹	New Construction	Recomplete	Diher Sol	•	
Final Abandonment Notice		Plug and Abandon Plug Back	Temporarily AWater Disposa		Cmt	
determined that the site is ready	•	other sid	<u>l</u> e	ACCEPTED FOR REC MG 6 1999 RIG. SGD.) GABY GOL	ORD	
14. I hereby certify that the forego	in a is take and correct					
Name (Printed/Typed) DAV	ID STEWART	Title	REGULAT	ORY ANALYST		
Signature	Set	Date	81-	5(99		
	THIS SPACE F	OR FEDERAL OR S				
Approved by		1	itie	Date		
	e attached Approval of this notice gai or equitable title to those rights o conduct operations thereon		Dffice			

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the U.J.ed States any faise, fictuous or traudulent statements or representations as to any matter within its jurisdiction.

ATTACHMENT 3160-5 OXY USA INC. OXY WODEN FEDERAL #1 SEC 23 T17S R27E EDDY COUNTY, NM

NOTIFIED BLM 7/14/99 OF SPUD. MIRU FWA-PETERSON #307, SPUD WELL @ 0600hrs MDT 7/15/99. DRILL 17-1/2" HOLE TO TD 225' & LOST RETURNS, DRY DRILL TO 250' & GAINED RETURNS, DRILL TO TD @ 400', 7/15/99, PUMP SWEEP. RIH W/ 13-3/8" 48# H40 CSG & SET @ 400'. M&P 100sx CL H W/ 10# GILSONITE + 10% HNB + 1% CaCl₂ FOLLOWED BY 163sx 65:35 C/POZ W/ 6% BENTONITE + 2% CaCl₂ FOLLOWED BY 200sx CL C W/ 2% CaCl₂, DISP W/ FW, PLUG DOWN @ 0045hrs MDT 7/16/99, CIRC 259sx CMT TO PIT, WOC. GENE HUNT W/ BLM WITNESSED CMT JOB. CUT OFF CASING, WELD ON STARTING HEAD, TEST TO 500#, OK. NU BOP & CHOKE MANIFOLD, TEST BLIND RAMS, PIPE RAMS, & HYDRIL TO 500#, OK, TOTAL-WOC-18hrs. BLM NOTIFIED OF BOP TEST, DID NOT WITNESS. RIH & TAG, DRILL OUT & DRILL AHEAD.

DRILL 11" HOLE TO TD @ 1800', 7/18/99, RUN FLUID CALIPER. RIH W/ 8-5/8" 32# K55 CSG & SET @ 1800'. M&P 475sx 65:35 C/POZ W/ 6% BENTONITE + 2% CaCl₂ + 5#/sx GILSONITE + $\frac{1}{4}$ #/sx CELLOFLAKES FOLLOWED BY 200sx CL C W/ 2% CaCl₂ DISP /FW, PLUG DOWN @ 2220hrs MDT 7/18/99, CIRC 184sx CMT TO PIT, WOC. JIM AMOS W/ BLM WITNESSED CMT JOB. PU BOP & SET SLIPS W/ 57000#. NU 5M RECTOR B SECTION, TEST SEALS TO 2000#, OK. TEST BLIND RAMS, PIPE RAMS, CHOKE LINES, CHOKE MANIFOLD AND SAFETY VALVES TO 5000#, OK. TEST HYDRIL TO 2500#, OK. TEST KILL LINE, MUD LINES, & CASING TO 2500#, OK, TOTAL WOC-18hrs. BLM NOTIFIED OF BOP TEST, DID NOT WITNESS. RIH & TAG, DO CMT, TEST TO 500#, OK, DRILL AHEAD.

19 - 19 **1** - 19

