

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-30577
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. S-136
7. Lease Name or Unit Agreement Name OXY MaH-O-Meal State 24260
8. Well No. 1
9. Pool name or Wildcat WC Red Lake Morrow, NE

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <u>Dry Hole</u>
2. Name of Operator OXY USA Inc. 16696
3. Address of Operator P.O. Box 50250 Midland, TX 79710-0250

4. Well Location Unit Letter <u>L</u> : <u>1800</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>22</u> Township <u>17S</u> Range <u>28E</u> NMPM <u>Eddy</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3610'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

DRILL 7-7/8" HOLE TO 10425', 4/1/99, CIRC HOLE, RIH W/ LOGS, POOH. REC PLUGGING PROCEDURES FROM MIKE STUBBLEFIELD- NMOC 4/3/99. RIH W/ OE DP TO 10100', SPOT 25sx CL H CMT. POOH LDDP TO 8150', SPOT 25sx CL H CMT. POOH LDDP TO 6858', SPOT 25sx CL C CMT. POOH LDDP TO 3610', SPOT 25sx CL C CMT. POOH LDDP TO 2150', SPOT 25sx CL C W/ 3% CaCl<sub>2</sub>. POOH LDDP TO 1600', CHC, WOC-3hrs. RIH & TAG CMT @ 2000', POOH LDDP TO 450', SPOT 30sx CL C CMT. POOH, SPOT 10sx CL C CMT SURF PLUG. JET & CLEAN PITS, RR 4/5/99. NMOC NOTIFIED BUT DID NOT WITNESS. CUT OFF CSG 3' BELOW GROUND LEVEL, WELD ON 1/2" STEEL PLATE, W/ 1" VALVE, INSTALL DRY HOLE MARKER, WELL P&A'D.

Post ID-2  
7-2-99  
P&H

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Regulatory Analyst DATE 6/16/99  
TYPE OR PRINT NAME David Stewart TELEPHONE NO. 9156855717

(This space for State Use)

APPROVED BY Jim W. Green TITLE District Supervisor DATE 10-15-99  
CONDITIONS OF APPROVAL, IF ANY: