

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-30659
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	NM-98809
7. Lease Name or Unit Agreement Name	Concho ACT State Com
8. Well No.	1
9. Pool name or Wildcat	Crow Flats Morrow
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3362' GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. Name of Operator  
YATES PETROLEUM CORPORATION

3. Address of Operator  
105 South 4th St., Artesia, NM 88210

4. Well Location BHL: 1980' FNL & 660' FEL of Section 8-T17S-R27E (Unit H, SENE)  
Unit Letter H : 1650 Feet From The North Line and 660 Feet From The East Line

Section 8 Township 17S Range 27E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3362' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 9000'. Reached TD at 8:15 PM 7-22-99. Tim Bussell, Drilling Foreman for Yates Petroleum Corporation received verbal permission to plug and abandon well from Mike Stubblefield w/OCD-Artesia. Well was plugged and abandoned as follows:

Plug #1: 8753-8653' - 30 sacks "H" Neat  
Plug #2: 7734-7634' - 35 sacks "H" Neat  
Plug #3: 5967-5867' - 40 sacks "C" Neat  
Plug #4: 4771-4671' - 50 sacks "C" Neat  
Plug #5: 2660-2560' - 45 sacks "C" Neat  
Plug #6: 1460-1360' - 50 sacks "C" and 3% CaCl2  
Plug #7: 0-50' - 10 sacks "C" Neat.

Released rig at 2:00 PM 7-25-99. Installed regulation abandonment marker. PLUGGED  
AND ABANDONED - FINAL REPORT. Plugging completed 7-25-99.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE Aug. 2, 1999  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep I DATE 5-3-00  
CONDITIONS OF APPROVAL, IF ANY