Form 3160-5 November 1994) STIN	UNIT STATI DEPARTMENT OF THE BUREAU OF LAND MAN DRY NOTICES AND REP	INTERIOR 311 S. 1 AGEMENT Artesia,	I Cons. Division st Street NM 88210-2834 3.				
Do not use abandonee	a this form for proposals to I well. Use Form 3160-3 (Al	o drill or to re-enter al PD) for such proposals	•	If Indian, Allottee or Tribe Name			
SUBMIT IN	TRIPLICATE - Other Inst	ructions on reverse	1. 1. 1. 1. 1. 1. 1. 1.	If Unit or CA/Agreement, Name and/or No.			
C) Oil Well XX Gas Wel	1 D Other	· • •	1 2015	Well Name and No.			
2. Name of Operator MURCHISON OIL & CAS INC				WILLIS FED #2			
DALLAS, TX. 75202-2883 (214) 95951414 (1) Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)							
4. Location of well (<i>roomye</i>	, Sec., 1., K., M., Or Survey Descript	-9 <u>5</u>	11 0155,535452	. County or Parish, State			
660' FSL & 6	60'FEL SESE(P) S	EC 28 T17S R27E		EDDY COUNTY, NEW MEXICO			
12. CHIECK	APPROPRIATE BOX(ES)	TO INDICATE NATU	RE OF NOTICE, REPO	DRT, OR OTHER DATA			
TYPE OF SUBMISSION	N	TYPE OF ACTION					
Notice of Intent		Deepen	D Production (Start/Re	sume) D Water Shut-Off			
	After Casing	C Fracture Treat	C Reclamation	Well Integrity			
🔯 Subsequent Report	Casing Repair	New Construction	C Recomplete	& Other Perforate,			
G Final Abandonment Notice	Change Plans	D Plug and Abandon	Temporarily Aband	on <u>Acidize & Fracture</u>			
	ice Convert to Injection	D Plug Back	Q Water Disposal	Stimulate			

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/IIIA. Required subsequent reports shall be filed within 30 days fullowing completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

> Trip in hole and tag PBTD at 9567'. Ran Cement Bond log from 9567' to top of cement at 4800'. Perforated 9528' to 9542' – 14 ft. with 29 holes. Acidize with 2000 GAL 71/2% HCL and 30% methanol. Swabbed well dry. Set CIBP at 9470' dumped 30' cement. Perforated 9370' – 9411' 9413-15', 9417-20' – 50 feet with 101 holes. Acidize with 2500 gal 71/2% HCL with 30% methanol. Swab well down. Making about 30 MCFD. Frac well with 60,000# 20/40 eceno prop and 63,000 gal of 70% CO2 Methanol Foam gel. Flow well back to pit and clean up. Flowing @ 600 MCFD and 50 PSI.

14. Thereby certify that the foregoing is true and correct Name (Printed/Typed) , MICHAEL S. DAUGHERTY	Title	VICE PRESIDENT		ATIONS		
Signature Muchael Margaetty	Date	3/30/00				
THIS SPACE FOR FEDE	ERAL OR	STATE OFFICE USE				
Approved by		Title		Date		
Conditions of approval, if any, are attached. Approval of this notice does not certify that the applicant holds legal or equitable title to those rights in the sul which would entitle the applicant to conduct operations thereon.		Office				

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or

