Submit 3 Copies To Appropriate District Office <u>District I</u>	State of New Mexico		Form C-103 CS Revised March 25, 1999					
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 South First, Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> 2040 South Pacheco, Santa Fe, NM 87505	OIL CONSERVATION DIVISION 2040 South Pacheco Santa Fe, NM 87505		WELL API NO. 30-015-30859 5. Indicate Type of Lease STATE S FEE 6. State Oil & Gas Lease No. 25137					
SUNDRY NOTICES (DO NOT USE THIS FORM FOR PROPOSALS DIFFERENT RESERVOIR. USE "APPLICATIO PROPOSALS.) 1. Type of Well: Oil Well Gas Well	7. Lease Name or Unit Agreement Name: Coyote Special "9" State Com.							
2. Name of Operator Chi Operating, Inc.	7. Well No.							
3. Address of Operator P.O. Box 1799 Midland, Texas 79702			8. Pool name or Wildcat Crow Flats: Morrow, SE Gas Pool 96840					
4. Well Location Unit Letter A : 990 feet from the North line and 725 feet from the East line								
Section 9	Township 17S	Range 2	SE NMPM	Eddy County				
10. Elevation (Show whether DR, RKB, RT, GR, etc.) GR - 3521								
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data         NOTICE OF INTENTION TO:       SUBSEQUENT REPORT OF:         PERFORM REMEDIAL WORK       PLUG AND ABANDON								
	HANGE PLANS	COMMENCE DRIL	LING OPNS.					
		CASING TEST AN CEMENT JOB	D D					
OTHER:		OTHER: COM	PLETION/CONTIN	JED 🕅				

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Last sundry notice dated 2/10/00 had attempted to frac the upper set of perfs 9785-804', job aborted, casing problem. 1/22/00, set Pkr w/plug on wireline @ 9960'. TIH w/Onoff tool & found collapsed pipe @ 5500'. Attempted to swage pipe out to 5578'. Could go no further. Ran DHV. Shot FP & pulled casing from 5420'. RU & cut dwn over csg stub to 5636'. Cut csg off @ 5605' & pld bad section. Ran in w/5 1/2" csg & Lead seal. Set seal & tstd to csg to 1000#. TIH w/onoff & cleaned out to Pkr. Latched on to Pkr & tstd Tbg to 1000#. Pulled plug out of Pkr & cleaned up frac to pit. Cleaned out sand to 9906'. Con't trying to cleanup. 3/20/00 fractured treated perfs w/ 54,500 gals Binary Foam & 50,000 lbs 20/40 Interprop. Cleaned up to pit. & Test.

	10112131415	167 149			
	68 00 A 34				
I hereby certify that the information above is true :			d belief.		
SIGNATURE	H B TIT	63		DATE_	4/17/00
Type or print name John W. Wolf		ausi	Telephone No.	915-685-5	001
(This space for State use) Jim W.	5330°	BUPERVISOR, L	ISTRU3 I	AL INC	1
APPPROVED BY	BGX TITLE	<b>BUEBINISON, L</b>			1 U 2000
Conditions of approval if any:			l	DATE	<u> </u>

onditions of approval, if any: