

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents of drill-stem tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.
7R	450	470	Show of oil & Gas
Queen	1198	1306	Show of oil & gas
San Andres	2790	2798	Show of oil
San Andres	2540	2549	Show of oil
San Andres	2035	2240	Oil & Gas
Premier	1652	1666	NA

38. GEOLOGICAL MARKERS			38. GEOLOGICAL MARKERS		
NAME	TOP		NAME	TOP	
	MEAS. DEPTH	TRUE VERT. DEPTH		MEAS. DEPTH	TRUE VERT. DEPTH
7R	425				
Queen	1120				
Grayburg	1318				
San Andres	1666				

RECEIVED
NOV 07 2000
BLM
ROSWELL