

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-015-31720

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
MURCHISON OIL & GAS, INC. (#015363)

3. Address of Operator
1100 MIRA VISTA BLVD. PLANO, TX. 75093-4698

4. Well Location
Unit Letter P : 1320 Feet From The SOUTH Line and 1000 Feet From The EAST Li
Section 2 Township 17S Range 28E NMMPM EDDY County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3579 GL 3601 KDB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spud well on 6/15/01 and drill 17 1/2" hole to 410'. Run 13 3/8" 68 #/FT K-55 BTC casing to 410'. Cement with 155 sx. of 35:65 POZ Class C + 6% D20 + 2% S1 + .25 pps D29 followed by 200 SX of Class C + 2% S1 + .25 pps D29. Circulate cement to surface. Bumped plug float held. Cut off conductor and 13 3/8" csg. Weld on wellhead. WOC 18 HRS. Test casing and BOP to 1000 PSI. Held OK. Drill plug and cement. Resume drilling operations with a 12 1/4" bit.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Michael S. Daugherty TITLE VICE PRESIDENT OPERATIONS DATE 7/17/01
TYPE OR PRINT NAME MICHAEL S. DAUGHERTY TELEPHONE NO. (972) 931-0700

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

07 2001