

YATES PETROLEUM CORPORATION
Little Cuevo Unit #1
Section 20-T17S-R18E
Chaves County, New Mexico


SUNDRY NOTICE CONTINUED (INTENT TO PLUG):

WOC. Tag plug at 1150' or higher.

7. Spot a 25 sack cement plug at surface.

8. Clean location and install regulation abandonment marker.

NOTE: Salt gel plugging mud will be placed between all plugs.



Rusty Klen
Operations Technician
October 3, 1997