

ć



S. Ning

2

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fel New Mexico E 000

St Cons. Cours.

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

Notice of Intention to Change Plans	Notice of Intention to Temporarily Abandon Well	Notice of Intention to Drill Deeper
Notice of Intention to Plug Well	Notice of Intention to Plug Back	Notice of Intention to Set Liner
Notice of Intention to Squeeze	Notice of Intention to Acidize	Notice of Intention to Shoot (Nitro)
Notice of Intention to Gun Perforate	NOTICE OF INTENTION (OTHER) Practure treat	NOTICE OF INTENTION (Other)
OIL CONSERVATION CO SANTA FE, NEW MEXICO		30 May 22, 1956 (Date)
Gentlemen:		
Following is a Notice of	Intention to do certain work as described below at the	
Gulf Oil Corporati	mpany or Operator)	
	of Sec. 2, T. 17-S, R. 39-5,NM	IPM., Anderson Pco
In order to inc	(FOLLOW INSTRUCTIONS IN THE RULES AN prease production it is proposed to fi	
1. Pull tu 2. Run ste 3. Run 2-7 at appr 4. Treat f 5. Pull tu		ND REGULATIONS) recture treat as follows: and pump if necessary. r in base of 5-1/2" casing il with 15,000# sand.
1. Pull tu 2. Run ste 3. Run 2-7 at appr 4. Treat f 5. Pull tu	bing, rods and pump. el line measurement, clean out with a //8" tubing with packer and set packer commately 2450!. Cormation with 10,000 gallens lease of bing and packer. Rerun tubing, rods	ND REGULATIONS) recture treat as follows: and pump if necessary. r in base of 5-1/2" casing 11 with 15,000# sand.
1. Pull tu 2. Run ste 3. Run 2-7 et appr 4. Treat f 5. Pull tu to prod	prease production it is proposed to finiting, rods and pump. The line measurement, clean out with a 1/8" tubing with packer and set packer commatoly 2450'. Cormation with 10,000 gallens lease of Ubing and packer. Rerun tubing, rods hotion. By	ND REGULATIONS) recture treat as follows: and pump if necessary. r in base of 5-1/2" casing 11 with 15,000# sand. and pump and return well