September 12, 1968

C. O. Fulton P. O. Box 1121 Artesia, New Mexico 88210

Re: Well Signs

Dear Mr. Fulton:

On September 10, 1968, an inspection was made of your Dublin Federal and Gulf B State leases in Section 3-17-29. This inspection revealed that the Dublin Federal Well No. 1 C had no well sign and that the Gulf B State well No. 1 D had an incorrect well sign.

Please have correct signs made and placed at these wells as required.

These leases and, the Dublin State lease, will be inspected for well signs after 30 days. Failure to post the required signs may result in loss of allowable.

Very truly yours,

OIL CONSERVATION COMMISSION

R. L. Stamets Geologist

RLS/bh

SECT SE CHERDER

1. 0. Fultur 1. 0. Rox 1131 1. 0. Rox 1131 1. 10. 11, Xix Marin (18821a)

## Re: Well Stgns

ANGLIDT ASM LEDT

On September 10. 1964, an inspection was made of your Doblin Seleral and Gulf 3 State Leased in Section 3-17-29. Chis 161960com revealed that the Publin refers! Wall No. 2 C had no well soyn and that the Gulf B State well No. 1 D had an incurser will star.

Aleass hrea poureri signs made and placed at trose walls an Mutral.

These Lasses and, the Bubits State Lease, will be inspected of well argne affor 30 days. Failure to post the sequired signs as could in Loss of allowable.

Yerk truth Aces.

DIE CONSERVATION COMMISSION

2. L. Stander Scolegist

da Edn