

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION
AUG 27 1976
O. C. C.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-741
7. Unit Agreement Name CAVE POOL UNIT
8. Form of Lease Name CAVE POOL unit
9. Well No. 38
10. Field and Pool, or Wildcat CAVE
12. County Eddy

SUNDARY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- Injection
2. Name of Operator JEM Resources Inc.
3. Address of Operator B ox 648 Artesia, N. Mex. 88210.
4. Location of Well UNIT LETTER D 660 FEET FROM THE N LINE AND 660 FEET FROM THE W LINE, SECTION 8 TOWNSHIP 17 RANGE 29 N.M.P.M.
15. Elevation (Show whether DF, RT, CR, etc.) 3641 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8 5/8 surface set at 321 & circulated. 5 1/2 set at 2425 with 150 sacks.
Top perf 2353. Top of Queen 1670. Base of salt 655.

Will set 20 sacks at 2300 & tag plug, shoot pipe & set 35 sacks stub plug.
If Queen is open will set 35 sacks 1730-1620, 35 sacks 700-600 & 35 sacks
370-270. 10 sacks & Marker at top.

Hole will be loaded with M.L.F. Cement will be portland type 2.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>W. A. Gressett</i>	TITLE Pres.	DATE 8-27-76
APPROVED BY <i>W. A. Gressett</i>	TITLE SUPERVISOR, DISTRICT II	DATE AUG 27 1976
CONDITIONS OF APPROVAL, IF ANY:		