

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION
OCT 5 1976

O. C. C.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Free <input type="checkbox"/>
5. State Oil & Gas Lease No. E-741
7. Unit Agreement Name CAVE POOL UNIT
8. Farm or Lease Name CAVE POOL Unit
9. Well No. 38
10. Field and Pool, or Wildcat CAVE - GRBG
12. County Eddy

SUNDARY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - "A" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER - Injection
2. Name of Operator JEM Resources Inc.		
3. Address of Operator Box 648 Artesia, N. Mex. 88210		
4. Location of Well UNIT LETTER D 660 FEET FROM THE N LINE AND 660 FEET FROM THE 1 LINE, SECTION 8 TOWNSHIP 17 RANGE 29 N.M.P.M.		
15. Elevation (Show whether DF, RT, GR, etc.) 3641 DF		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

8 5/8 set at 321. 5 1/2 set at 2425. Top perf 2353. Top of Queen 1670. Base of salt 655.

Set 20 sacks at 2300 & tagged at 2130. Shot pipe at 1800 & pulled out. Set 35 sacks stub plug & 35 sacks at 1720. 35 sacks at 700 & 35 sacks at 370. Tagged at 314 & set 15 sacks additional. Tagged at 250. Set 10 sacks & Marker at top.

Hole was loaded with M.L.F. Cement was Portland type 2.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Walt Bell* TITLE Pres. DATE 10-5-76

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: