

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO CONSERVATION COMMISSION

JUN 14 1976

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

O. C. C.

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CLEAN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - M (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name <b>CAVE POOL UNIT</b>
2. Name of Operator <b>JEM Resources Inc.</b>	8. Farm or Lease Name <b>CAVE POOL</b>
3. Address of Operator <b>P.O. Box 648 Artesia, N. Mex. 88210</b>	9. Well No. <b>43</b>
4. Location of Well UNIT LETTER <b>G</b> <b>1980</b> FEET FROM THE <b>N</b> LINE AND <b>1980</b> FEET FROM THE <b>E</b> LINE, SECTION <b>8</b> TOWNSHIP <b>17</b> RANGE <b>29</b> N.M.P.M.	10. Field and Pool, or Wildcat <b>CAVE</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3612 DF</b>	12. County <b>Eddy</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7 5/8 Surface set at 687 & Circulated. 4 1/2 set at 2460 in 6 3/4 hole & cemented with 75 sacks. Top of salt 436, top of cement 1925, top perf 2373.

Set 25 sacks at 2354 & tagged plug at 2040, shot pipe at 1900 & set 35 sax. Set 35 sacks at 700 & tagged at 637. Set 10 sacks & Marker at top. Completed 5/19/76. Hole was loaded with mud laden fluid. Cement was Portland type 2.

P + A 5-19-76

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L. D. D. S. Jr. TITLE PRES DATE 6-14-76

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

