

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

JUN 14 1976

O. C. C.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. e-4200

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO ALTER OR PLUG DATA TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Injection	7. Unit Agreement Name CAVE POOL UNIT
2. Name of Operator JEM Resources Inc. ✓	8. Farm or Lease Name CAVE POOL
3. Address of Operator B ox 648 Artesia, N. Mex. 88210	9. Well No. 44
4. Location of Well UNIT LETTER H 1980 FEET FROM THE N LINE AND 660 FEET FROM THE E LINE, SECTION 8 TOWNSHIP 17 RANGE 29 N.M.P.M.	10. Field and Pool, or Wildcat CAVE
15. Elevation (Show whether DF, RT, GR, etc.) 3619 DF	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7 5/8 Surface set at 715 & circulated. 4 1/2 casing set at 2449 in 6 3/4 hole with 75 sacks. Top of Queen 1684, Salt 450, top perf 2401, top of Cement 1875.

Set 15 sacks at 2300 & tagged plug at 2110, shot pipe ⁰¹⁸⁴⁰ & set 35 sacks at 1800. set 35 sacks at shoe of surface. Found hole in surface & squeezed 25 sacks. set 10 sacks & Marker at top. Completed 5/24/76. Hole was Loaded with Mud Laden Fluid, & Cement was Portland type 2.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *W. H. Davis* TITLE Pres. DATE 6-14-76

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

Q 3712 027

Q 3712 027

Q 3712 027
Q 3712 027