



**marbob**  
energy corporation

May 1, 2002

Oil Conservation Division  
1301 W. Grand Ave.  
Artesia, NM 88210

Attn: Gerry Guye

Re: Inspection #GEG0202550305  
Boyd Dodd B #5  
P-11-17S-29E  
30-015-02950




Gerry:

In response to your letter regarding the above referenced inspection (copy attached), the violations indicated have now been corrected and arrangements can be made to re-inspect the well.

Thank you for your help in this matter. If you have any questions or need further information, please don't hesitate to contact me.

Sincerely,

  
Diana J. Cannon  
Production Analyst

*Compliance closed  
for.*

4/30/02



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**GARY E. JOHNSON**

Governor

**Betty Rivera**

Cabinet Secretary

APR 23 2002

**Lori Wrotenbery**

Director

**Oil Conservation Division**

*Field Inspection Program*

*"Preserving the Integrity of Our Environment"*

22-Apr-02

**MARBOB ENERGY CORP**

PO BOX 227

ARTESIA, NM 88211-0227



Dear Operator:

The following inspection(s) indicate one or more violations as described in the detail section below. The inspection(s) indicates that the well, equipment, location or operational status failed to meet standards of the New Mexico Oil Conservation Division. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section below indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division.

Please notify the proper district office of the Division of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

## **INSPECTION DETAIL SECTION**

**BOYD DODD B 005**

**P-11-17S-29E**

**30-015-02950-00-00**

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
04/22/2002	MIT Witnessed - Br	Gerry Guye	Yes	No	5/24/2002	iGEG0202550305

**Comments on Inspection:** Records this office show 5 1/2 casing cemented with 100 sx cement. Since the production casing was not circulated, the casing must be plumbed to the surface and a valve installed on which a gauge may be placed to monitor the 5 1/2 annulus.

Thank you for your prompt attention to this matter and your efforts in helping to protect our environment and the infrastructure of the oil and gas industry.

Sincerely,

Oil Conservation Division, District II

OK - FIXED  
PER DOYLE  
4/1/02

**Note:** Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.