## UNITED STATES SUBMIT IN TRIPLICATE\* (Other instructions on re-

Form approved.
Rudget Bureau No. 42-R1424.

DEPARTMENT OF THE INTERIOR	(Other instructions o verse side)	n re-	5. LEASE DESIGNATION AND SERIAL NO
GEOLOGICAL SURVEY			LC 028731 (b)

GEOLOGICAL SURVEY			LC 028731 (b)
SUNDRY N (Do not use this form for I Use "AP]	OTICES AND REPORTS ( proposals to drill or to deepen or plug be period for permit—" for such proposals to drill or to deepen or plug be permit to be	ON WELLS  pack to a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS WELL OTH	/ <	ALCEIVED	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	7	KIT 1 © 1982	8. FARM OR LEASE NAME
Sun Oil Company 3. ADDRESS OF OPERATOR	7 50 5 1600 SON		M. Dodd -B-
P. O. Box 1861	- Midland, TX 79702R	Test to comment	9. WELL NO.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*			7 10. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface  1980' FNL & 1980' FWL Unit Ltr. "F"			Grayburg Jackson-SR-Q-G-SA 11. SEC., T., B., M., OR BLK. AND
130	SO THE WISSO TWE	, , , , , , , , , , , , , , , , , , ,	SURVEY OR AREA
14. PERMIT NO.	15. ELEVATIONS (Show whether DF	. RT. GR. etc.)	Sec. 14, T 17 S, R 29 E
	3628' GR	, 112, 011, 000.)	Eddy NM
16. Charl			
	Appropriate Box To Indicate N		
NOTICE OF	INTENTION TO:	SUBS	EQUENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*. X
REPAIR WELL (Other)	CHANGE PLANS	(Other)(Note: Report resu	lts of multiple completion on Well npletion Report and Log form.)
	D OPERATIONS (Clearly state all pertinen irectionally drilled, give subsurface locat		es, including estimated date of starting any tical depths for all markers and zones perti-
WELL HAS POSSIBLE TO MIRU. ATTEMPT TO RILINED TBG & PKR. SET CIBP ON WL @ 2407" CSG @ 1000' W/4 NPSI W/FULL CIRC OUT DISPLACED 100 SX "C'& PKR. PERF 7" CSG BH, 5 BPM @ 400 # PSPLACED 10' SURF PLUCRR & CLEAN LOCATION	TEX WATERFLOOD WHICH WAS BG OR CSG LEAK, P&A PER LS PKR, SHEARED PKR DISP DO' DUMPED 7 SX (35') ON WAY SHOT. RAN PKR ON 2 BH. ' NEAT CMT W/FULL CIRC OF 0 500' W/4 JSPF CMTD DO SI DISPLACED CMT TO 350' G, CUT OFF WH & INSTALL	NMOCC REQUIREMENTS. PL HOLE W/BRINE & MU  I CIBP. PRESS TEST 3/8" TBG. SET PKR  OUT BH TO 900' THRU OWN 7" CSG W/100 SX SIP 150#.	JD. POH W/2 3/8" CMT CSG 1000# PSI OK. PERF @ 900'. EIR 5 BPM @ 400#
18. I hereby certify that the forego	1/:		0.11.01
SIGNED	Tilliams TITLE SY	. Accounting Assist	
(This space for Federal or Stat	e office use)		APPROVED
APPROVED BYCONDITIONS OF APPROVAL,	IF ANY:	<del></del>	DATE
			0CT 1 5 1982

\*See Instructions on Reverse Side

DISTRICT SUPERVISOR