

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

RECEIVED

NOV 29 1973

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>50710</b>
7. Unit Agreement Name
8. Farm or Lease Name <b>Continental "U" State</b>
9. Well No. <b>2</b>
10. Field and Pool, or Wildcat <b>Grayburg Jackson</b>
12. County <b>Eddy</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER- **ARTESIA, OFFICE**

2. Name of Operator  
**Sun Oil Company**

3. Address of Operator  
**P. O. Box 1861, Midland, Texas 79701**

4. Location of Well  
UNIT LETTER **D**, **330** FEET FROM THE **North** LINE AND **990** FEET FROM  
THE **West** LINE, SECTION **15** TOWNSHIP **17-S** RANGE **29-E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
**3576 (10' above GL)**

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1.) MIRU Pool Co. pulled rods 9-20-73.
- 2.) Circulated hole w/9.5 # mud. spotted 15 sx. cmt. plug @ 2450-2320'. 9-21-73
- 3.) Weld on pull nipple, shot csg. @ 1918. 9-21-73
- 4.) Pumped 30 sx. cmt. plug @ 1918-1818. 9-22-73
- 5.) Spotted 30 sx. cmt. across Queen, plug @ 1780'-1680'. 9-22-73
- 6.) Pulled csg. and ran tbg., spotted 35 sx. cmt. plug @ 780'-680', 50' in & out of surf. csg.
- 7.) Spotted 10 sx. cmt. in top of csg., weld cap on 7-5/8", install marker. 9-22-73

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Charles Gray</u>	TITLE <u>Proration Clerk</u>	DATE <u>11-28-73</u>
APPROVED BY <u>Lester McCombs</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>DEC 3 1973</u>
CONDITIONS OF APPROVAL, IF ANY:		

