Form 3160-5 (June 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Jil Cons. N.M. DIV-Dist. 2 FORM APPROVED 1301 W. Grand Aven Preau No. 1004-0135 Artesia, NM 5.88200 nation and Serial No. LC028731B

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE

7. If Unit or CA. Agreement Designation

1. Type of Well

X Oil Well

Gas Well

Other

2. Name of Operator

MARBOB ENERGY CORPORATION

3. Address and Telephone No

PO BOX 227, ARTESIA, NM 88210 505-748-3303

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660 FNL 660 FEL, SEC. 15-T17S-R29E, UNIT A

8. Well Name and No.

MARY DODD "B" #11

9 API Well No.

30-015-02993

10. Field and Pool, or Exploratory Area GRBG JACKSON SR QN GRBG SA

11. County or Parish, State

EDDY CO., NM

## CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12.

TYPE OF SUBMISSION

Final Abandonment Notice

TYPE OF ACTION

Notice of Intent

X Subsequent Report

X Abandonment

Recompletion

Plugging Back

Casing Repair

Altering Casing

Other

Change of Plans

**New Construction** 

Non-Routine Fracturing

Water Shut-Off

Conversion to Injection

Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinet details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markders and zones pertinent to this work.)\*

PLUG AND ABANDON THE WELL AS FOLLOWS:

1/8/02 - POOH W/ RODS & TBG. HAUL TO BKU YARD. HAUL 80 JTS 2 3/8" TBG FROM YARD.

1/9/02 - SET CIBP @ 2365'. DUMPED 5 SX CMT ON CIBP. PERF CSG @ 910' (4 HOLES). SET RETAINER @ 802'. PUMPED 75 SX CLASS "C" CMT CONT 2% CACL2. PERF CSG @ 550' (4 HOLES). \*\*\*NOTE: HOMER SANZE W/ THE BLM WAS ON LOCATION & WITNESSED ABOVE WORK

1/10/02 - SET RETAINER @ 382'. PUMPED 127 SX CLASS "C" CMT CONT 2% CACL2. CMT CIRCULATED BETWEEN 8 5/8" & 5 1/2" CSG. REMOVE SETTING TOOL. FILL 5 1/2" CSG W/ 60 SX CLASS "C" CMT. POOH W/ TBG & TOPPED CSG OFF W/ CMT. DUG DOWN AROUND CSG 3' FOR CUT-OFF FOR DRY HOLE MARKER. RD & CLEAN LOCATION. \*\*\*NOTE: JIM AMOS W/ THE BLM VISITED THE LOCATION ON THIS DATE. MARR'S WELDING GIVEN INFORMATION FOR DRY HOLE MARKER & WILL BE INSTALLED.

Approved as to plugging of the well bore. Liability under bond is retained until surface restoration is competed.

certify that the foregoing is true and correct

PRODUCTION ANALYST

01/14/02

(This space for Federal or State office use)

Approved by (ORIG. SGDV) ALEXIS C. SWOBODA Conditions of approval, if any:

Title

PETROLEUM ENGINEER

JAN 1 8 2002

Accepted for record

Tit sta

adjy and willfully to make to any department or agency of the United States any false, fictitious or fraudulent

TMOV. C.A. 10 UNSAUR EOITEO LLEMROSA

01:6 HA 21 HAL SOOS

BECEINED