

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN _____ ICATE*
(Other instruct. on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

028731-3

EFFECTIVE ~~SUNDAY~~ **NOTICES AND REPORTS ON WELLS**
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
SUN OIL COMPANY - DX DIVISION PERMIT - for such proposals.)

1. NAME CHANGED TO **SUNRAY DX OFF CO.**
OIL GAS
WELL WELL
SUN OIL COMPANY
2. NAME OF OPERATOR **SUN OIL CO., DX DIVISION**
Sunray Drilling Company
3. ADDRESS OF OPERATOR **P. O. Box 1416, Roswell, New Mexico**
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
660' FNL & 1980' FEL, Section 15, T-17-S, R-29-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3587 CL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

M. Dodd "B"

9. WELL NO.

16

10. FIELD AND POOL, OR WILDCAT **R3262**

Square Lake *Gray by Jackson*
11. SEC., T., R., M., OR BLE AND
SURVEY OR AREA

Sec. 15, T-17-S, R-29-E

12. COUNTY OR PARISH 13. STATE

Seddy

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Convert to Injection

X

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

EFFECTIVE 4-1-70

SUN OIL COMPANY - DX DIVISION

NAME CHANGED TO **P. O. BOX 2880**

SUN OIL COMPANY DALLAS, TEXAS 75201

RECEIVED

JUN 22 1967

ARTESIA, OFFICE

1. Move in and rig up workover rig.
2. Pull 2 3/8" tubing.
3. Run 2 3/8" tubing w/Model "AD" Packer.
4. Set Packer at 2388.
5. Installed injection well head.
6. Commence water injection.

Approval authorized by Commission Order R-3013 WFX 258.

18. I hereby certify that the foregoing is true and correct

SIGNED

John Hastings

John Hastings

TITLE

District Engineer

DATE **June 16, 1967**

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

RECEIVED
JUN 20 1967
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

APPROVED
JUN 21 1967

R. L. BECKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 7: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-498229

947-041

APPROVED
JAN 5 1964
U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT