

NEW MEXICO STATE LAND OFFICE
SANTA FE, NEW MEXICO

DEPARTMENT OF THE STATE GEOLOGIST
SANTA FE

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

Mr. **E. H. Wells** Roswell, N. Mex., June 1st 1934
Santa Fe, New Mexico.

Dear Sir:

You are hereby notified that it is our intention to abandon Harry Leonard, Inc., Well
No. 1 in NW 1/4 of Sec. 21 of T. 178, R 29E,
N. M. P. M., Harry Leonard, Inc GAS Field, Eddy County.
We plan to commence work on June 6th, 1934.

The reasons for wishing to abandon the well are as follows:

No longer profitable to operate.

The present condition of the well is as follows:

Contains 2200' of 8-1/4" pipe.

The work which we propose to do in abandoning the well is as follows:

Place a cement plug in the gas producing strata; pull the 8-1/4" pipe; mud to top, cementing 4' marker.

DUPLICATE

Approved JUN 11 1934 1934

Except as follows:

[Signature]
State Geologist or Oil and Gas Inspector.

Sincerely yours,

HARRY LEONARD, INC.,

Company or Operator.

By [Signature]
Position Pres.

Send communications regarding this well to

Name **HARRY LEONARD, INC.,**

Address **Roswell, New Mexico**