

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M.O.
11 S. "st
tesia, N

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

MARBOB ENERGY CORPORATION

3. Address and Telephone No.

P.O. DRAWER 227, ARTESIA N.M. 88210 505-748-3303

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

SEC. 22 T-17-S R-29-E 660 FSL 660 FEL

5. Lease Designation and Serial No.

LC-028731-A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

M.DODD "A" #4

9. API Well No.

30-015-03030

10. Field and Pool, or Exploratory Area

GRBG - JACKSON. QNSA

11. County or Parish, State

EDDY, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- Spot 150 sxs. cement w/ 3% col.c from 2,539' and w.o.c., rig up wire line. tag. plug at 2315' is too low
- Respot. 35 sxs. w/ 3% col.c. from 2,315' and w.o.c. 4 hrs. Rig up wire line. tag. plug @ 1,907'
- Circ. hole. w/ mud.
- Perf 4 squeeze. hole at 1,055' in 7" csg.
- RIH w/ 7" AD-1 pkr. set at 522' sqz. 100 sxs. cement. w/ 3% col.c. disp. cement. below of pkr.
- Rig up wire line. RIH S/B cement. plug. is too low.
RIH w/ 7" AD-1 pkr. set at 522' sqz plug w/100 sxs. cement. w.o.c.
Rig up wire line and tag cement. plug at 538'
- Perf. 4 squeeze. holes at . 350' top of salt.
RIH w/7" AD-1 pkr. set at 150' sqz. 35 sxs. cement. w/ col.c. w.o.c. 4 hrs.
Rig up wire line RIH w/ S/B cement. plug is too low.
RIH w/7" AD-1 pkr. set at 150' sqz. 35 sxs cement. into of perfs. at 350' disp. cement. below. of pkr.
- Rig up wire line. RIH w/ S/R and. tag. cement. plug at 170'
Perf. 4 squeeze. holes at 50' in 7" csg. pumped and circ. cement. to surg. w/ 50 sxs.
Cut well head. off. set PXA marker. 7-11-97

BUREAU OF LAND MGMT.
ROSWELL OFFICE

ACCEPTED FOR RECORD

RECEIVED
SEP 11 1997
ELM

SEP 21 10 38

Post ID-2
9-26-97
RFA

14. I hereby certify that the foregoing is true and correct

Signed

Rudy Gutierrez

Title

Supervisor

Date

8-9-97

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any: