SUPERVISION.

OIL AND GAS DEVELOPMENT

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

May 20, 1937

MAT 2 2 1101 A

Re: Dodd Lease Las Cruces 028731-A.

Barnsdall Oil Company Box 466 Pecos, Texas

Gentlemen:

Receipt is acknowledged of your "Subsequent Report of Acidizing" dated May 14, 1937, covering well No. 5 on the subject land in SE¹ of section 22, T. 17 S., R. 29 E. You report work completed as follows:

"The above well was treated with 4000 gallons of acid from 2600' to 2750'. Did not respond to treatment. In fact, the treatment decreased the production.

"Well	produced	natural approximately	25	bbls.	per	24	hrs.
11		after shot	100	bbls.	per	24	hrs.
Ħ	11 11	after acidizing	82	bbls.	in	48	hrs.

"Work done by Dowell Incorporated."

Your "Subsequent Report of Acidizing" is hereby approved.

THOMAS G. TAYLOR

Acting Engineer in Charge.

TGT/1