

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR. DATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

028731-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such purposes.)

RECEIVED

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Sunray DX Oil Company		8. FARM OR LEASE NAME M. Dodd "A"	
3. ADDRESS OF OPERATOR P. O. Box 1416 - Roswell, New Mexico		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit N. 330' FSL, 1650' FWL		10. FIELD AND POOL, OR WILDCAT Grayburg - Jackson	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 22, T-17-S, R-29-E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3536 DF		12. COUNTY OR PARISH Eddy	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☒ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Move in and rig up workover rig.
2. Stripped out rods and tubing. Tubing parted at 1017 ft. Pulled rods and pump.
3. Run Bowen over-shot (5-1/4") with 7" skirt. Stopped at 960'. Pulled over-shot out of hole.
4. Ran 7" impression block to 961'. Block showed that casing was collapsed.
5. Ran 2-3/8 center spear to 962'. Unable to drive through.
6. Attempted to pull 8-5/8" casing. Unsuccessful.
7. Ran 5-1/4" casing swedge on 4, 4-3/4" DC and bumper sub.
8. Started swedging on 8-5/8" casing at 960'. Swedge went to 963' and went outside casing. Casing parted.
9. Attempted to pull casing again. Unsuccessful.
10. Ran Baash-Ross casing cutter. Cut casing at 700'.
11. Attempted to pull. Unsuccessful
12. Cut casing at 600'.
13. Attempted to pull. Unsuccessful.
14. Circulated water around casing. Good circulation.
15. Worked casing up hole approximately 20'. Stuck again.
16. Repair unsuccessful, prepare to P&A.

RECEIVED

OCT 20 1967

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED John HastingsTITLE District EngineerDATE 10-19-67

(This space for Federal or State office use)

APPROVED BY [Signature]
CONDITIONS OF APPROVAL, IF ANYTITLE DISTRICT ENGINEERDATE OCT 20 1967

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.