

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED

MAR 14 '88

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-1266	
7. Unit Agreement Name	
8. Farm or Lease Name	
G-J West Coop Unit	
9. Well No.	
26	
10. Field and Pool, or Wildcat	
Grbg Jackson SR Q Grbg SA	
12. County	
Eddy	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT PERMIT. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>
Name of Operator		
Marbob Energy Corporation		
Address of Operator		
P.O. Drawer 217, Artesia, N.M. 88210		
Location of Well		
UNIT LETTER	M	330
FEET FROM THE		South
LINE AND		990
FEET FROM		
THE	West	LINE, SECTION 22
TOWNSHIP		17S
RANGE		29E
NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		
3528' GR		

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to plug & abandon well as follows:

\*Lead to new mud  
Set cmt plug from 2771-2057', tag plug, set 100' plug @ 1400-1300', set 100' plug @ 1190-1090, set 100' plug @ 682-582', set 100' plug @ 292-192, set 15sx plug at surf, install dry hole marker and clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Rhonda Nelson TITLE Production Clerk DATE 3/10/88

Original Signed By  
Mike Williams

APPROVED BY Oil & Gas Inspector TITLE Notify N.M.O.C.C. in sufficient time to witness DATE MAR 14 1988  
CONDITIONS OF APPROVAL, IF ANY: Plugging

