Carlsbad, New Mexico September 14, 1933

Dr. E. H. Wells, State Geologist, Socorro, New Mex.

Dear Dr. Hells:

Referring to the SG-101 for the Harry Leonard Inc., State #9 well, located in Sec. 22, T. 17 S., R. 29 E.

Mr. Leonard has requested that the location be changed to read as follows: 2310' South of the North line and 2310' East of the dest line. You will probably notice that I changed part of it.

Please make this correction on the Original which you have there at Socorro.

Very truly yours,

J. D. Hunter, Inspector.