

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

LC- 028731-A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Marbob Energy Corporation

3. Address and Telephone No.

P.O. Drawer 227, Artesia, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1650 FSL 1650 FEL, Sec.22, T-17S, R29E, Unit j

8. Well Name and No.

M. Dodd "A" #12

9. API Well No.

20-015-03047

10. Field and Pool, or Exploratory Area

Grbg Jackson Sr Q Grbg Sa

11. County or Parish, State

Eddy County, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other


- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Notify BLM 24 hrs. before starting

1. POH W/ rod & tubing
2. Set 5 1/2" CIBP @ 3100 (Perf 3155 TO3191) - 35' cmt on top
3. Perf 5 1/2" @ 902 (base salt 852) sqz. 45 sx. woc tag
4. Spot 180" plug (8 5/8 shoe @339 top salt 405) circulate cmt to surface woc tag (Perf. @ 700 circ cmt to surface 1/8/93)
5. Spot 60 plug @ surface
6. Cut off well head install dry hole marker



14. I hereby certify that the foregoing is true and correct

Signed Walter Brown
(This space for Federal or State office use)

Title Agent

Date 03/13/02

Approved by _____
Conditions of approval, if any:

Title _____

Date _____