0. 0. 0. CORN

## UNITED STATES DEPARTMENT OF THE INTERIOR

LANNIE TO BUSINE	ND REPORTS ON WELLSUL 9 1962
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.  SUBSEQUENT REPORT OF ALTERING CASING.  SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.  SUBSEQUENT REPORT OF ABANDONMENT.  SUPPLEMENTARY WELL HISTORY.

(INDICATE	ABOVE BY CHECK MARK NATURE OF REPORT	T, NOTICE, OR OTHER DATA)
	loss Hill	a, New Mexico July 6 , 19 6
Well No. 6 is located	ft. from $\left\{S\right\}$ line and	1 1960 ft. from E line of sec. 23
Section 23 (1/4 Sec. and Sec. No.)	(Twp.) (Range)	(Meridian) RECEIVE
Grayburg—Jackson (Field)	(County or Subdivision)	(State or Appriory)
Γhe elevation of the derrick fl	oor above sea level is 3578	ft.
	DETAILS OF WOR	
State Hames of any expected depths to ox	ing points, and all other important pro	gths of proposed casings; indicate mudding jobs, cemen posed work)
	mter well flowed 30 BOPS pressure it was decided	to defer proposed fracture
I understand that this plan of work m	ust receive approval in writing by the Geol	logical Survey before operations may be commenced.
Company General Americ	en Oil Company of Texas	
Address P. O. Box 416	·	- 11 \
Loco Mills, No	w Mexico	By KAtion
	Ti	% J. haard tle <b>District Superintendent</b>