Drawer DD

Form Approved. Budget Bureau No. 42-R1424

Form 9-331 Dec. 1973

UNITED STATEStesia, NM 88210

SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS CONTINUED THE TOTAL PROPERTY OF THE NATION OF PROPERTY OF THE PARTY OF THE	DIVITED STATES	5. LEASE T.C-028	79/-0
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to differ to despen or plug back to a different serverour, the Femal Page 12 of the respen or plug back to a different 1. cil. #EX	DEPARTMENT OF THE INTERIOR	LÇ-028784-c	
SUNDRY NOTICES AND REPORTS ON WELLS. (Deather the firm for proposels to drill or to despen or plug back to a different reservoir, the form 5-31-C for such proposels.) 1. oii	and the second of the second o	6. IF INDIAN, ALLOTTEE C	· · · · · · · · · · · · · · · · · · ·
1. oil	SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAM	T
### WELL NO. 1. NAME OF OPERATOR PHILLIPS OIL COMPANY (Successor General American Oil Co. of Texas by acquisition 2. NAME OF OPERATOR PHILLIPS OIL COMPANY (Successor General American Oil Co. of Texas by acquisition 3. ADDRESS OF OPERATOR ROOM 401, 4001 Penbrook St., Odessa, Texas 79762 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: Unit J, 1980' FS&E AT TOP PROD. INTERNAL: AT TOTAL DETTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE. REPORT, OR OTHER DATA SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOT OR ACIDIZE ***TEXAS WELL **TOTAL ORDINAL TO SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT **SUBSEQUENT REPORT OF: TEST WATER CASING MULTIPLE COMPLETE Other and perforations and additional pay 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and tones pertinent to this work.) 1. Clean out to TD 2. Acidize and fracture treat the San Andres open hole (+2800-3200') 3. Perforated selected Grayburg/San Andres (+2350-2800') 4. Acidize and fracture treat the San Andres open hole (+2800-3200') 5. Acidize and fracture treat the San Andres (+2350-2800') 6. Return well to production. Subsurface Safaty Vaive: Manu. and Type TITLE Space in the additional pay DATE (#FE. TITLE Space in the state of the state	(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME	JUN 08 1984
2. NAME OF OPERATOR PHILLIPS OIL COMPANY (Successor) General American 011 Co. of Texas by acquisition 3. ADDRESS OF OPERATOR Room 401, 4001 Penbrook St., Odessa, Texas 79762 4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17 below), AT SURFACE; Unit J, 1980¹ FSSE AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE WHATER CASING HULLIPHE COMPLETE CHANGE ZONES ABANDON' 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, moustained and true vertical depths for all markers and zones pertinent to this work,)* 18. Clean out to TD 2. Acidize and fracture treat the San Andres open hole (+2800-3200¹) 3. Perforated selected Grayburg/San Andres (+2350-2800¹) 5. Acidize and fracture treat the San Andres (+2350-2800¹) 6. Return well to production. Subsurface Safety Valve: Manu. and Type Subsurface Safety Valve: Manu. and Type TILLESpecialist THLESpecialist THLESpecialist THLESpecialist THLESpecialist DATE GLOCK TARM AND SURVEY OR AREA 6c. 25.T-17-S,R-29-E 12. COUNTY OR PARISH 13. STATE Eddy 14. APINO. 15. ELEVATIONS (SHOW DF, KDB, AND WD) 3583 CBB > FT 16. ELEVATIONS (SHOW DF, KDB, AND WD) 3583 CBB > FT 17. EACH TO THE MENT OF THE BOOK TO T	1. oil gas other		
General American oil Co. of Texas by acquisition General American oil Co. of Texas by acquisition ADDRESS OF OFTRATOR Room 401, 4001 Penbrook St., Odessa, Texas 79762 LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AI SUBFACE: Unit J, 1980' FS&E AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE WITH THE COMPLETE CHANGE ZONES ABANDON' (other) add perforations and additional pay 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) 1. Clean out to TD 2. Actidize and fracture treat the San Andres open hole (+2800-3200') 3. Perforated selected Grayburg/San Andres (+2650-2800') 4. Actidize and fracture treat the San Andres (+2650-2800') 5. Actidize and fracture treat the Grayburg (+ 2350-2650') 6. Return well to production. Subsurface Safety Valve: Manu. and Type TILESPECIALIST THESPECIALIST ORIGINAL APPROVED BY APPROVED BY APPROVED BY THE SERVE TO Feer and State office use) APPROVED BY APPROVED BY APPROVED BY THE SERVE TO Feer and State office use) APPROVED BY			ARTESIA, OFFICE
Odessa, Texas 79762 4. LICATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: Unit J, 1980' FSSE AT TOP PROD. INTERVAL: AT TOTAL DEFTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT TOTAL DEFTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT TOTAL DEFTH: (NOTE: Report results of multiple completion or zone change on form 9-330.) (NOTE: Report results of multiple completion or zone change on form 9-330.) (NOTE: Report results of multiple completion or zone change on form 9-330.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pert	o General American Oil Co. of Texas by acquisition	10. FIELD OR WILDCAT NA	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: Unit J, 1980' FS&E AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF RACTURE TREAT X15X SHOOT OR ACIDIZE X15X REPAIR WELL PULL OR ALTER CASING NULTIPLE COMPLETE OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and conse pertinent to this work.) 1. Clean out to TD 2. Acidize and fracture treat the San Andres open hole (+2800-3200') 3. Perforated selected Grayburg/San Andres (+2350-2800') 4. Acidize and fracture treat the San Andres (+2350-2800') 5. Acidize and fracture treat the San Andres (+250-2800') 6. Return well to production. Subsurface Safety Valve: Manu. and Type Senior Engineering THE Special ist DATE (44.8.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.	3. ADDRESS OF OPERATOR Room 401, 4001 Penbrook St.,	Grayburg-Jacks 11. SEC., T., R., M., OR BI	OD AND SURVEY OR
AT SURFACE: Unit J, 1980' FS&E AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 17. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE WILL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON' (other) add perforations and additional pay 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and frue vertical depths for all markers and zones pertinent to this work.)* 1. Clean out to TD 2. Acidize and fracture treat the San Andres open hole (+2800-3200') 3. Perforated selected Grayburg/San Andres (+ 2350-2800') 4. Acidize and fracture treat the San Andres (+ 2350-2800') 5. Acidize and fracture treat the Grayburg (+ 2350-2650') 6. Return well to production. Subsurface Safety Valve: Manu. and Type Senior Engineering THESpecialist DATE (ALAS H) New Mexico 14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD) 3583'	4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA	: ·
AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE. REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE X-10X REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) add perforations and additional pay 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 1. Clean out to TD 2. Acidize and fracture treat the San Andres open hole (+2800-3200*) 3. Perforated selected Grayburg/San Andres (+2350-2800*) 4. Acidize and fracture treat the San Andres (+2350-2800*) 5. Acidize and fracture treat the Grayburg (+ 2350-2650*) 6. Return well to production. Subsurface Safety Valve: Manu. and Type Subsurface Safety Valve: Manu. and Type TILE DATE ALAGA TILE DATE ALAGA TILE DATE ALAGA DATE 3-22-84 DATE ALAGA DATE ALAGA TILE DATE ALAGA TILE DATE ALAGA	below.)) 	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE. REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND WD) REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT X-15X SHOOT OR ACIDIZE X-15X SHOOT OR ACIDIZE X-15X SHOOT OR ACIDIZE X-15X SHOOT OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) add perforations and additional pay 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 1. Clean but to TD 2. Acidize and fracture treat the San Andres open hole (+2800-3200¹) 3. Perforated selected Grayburg/San Andres (+2350-2800¹) 4. Acidize and fracture treat the San Andres (+2650-2800¹) 5. Acidize and fracture treat the Grayburg (+2350-2650¹) 6. Return well to production. Subsurface Safety Valve: Manu. and Type Subsurface Safety Valve: Manu. and Type TITLE DATE ALAGA TITLE DATE DATE 3-27-84			
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF		14. API NO.	•
REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) add perforations and additional pay 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 1. Clean out to TD 2. Actidize and fracture treat the San Andres open hole (+2800-3200*) 3. Perforated selected Grayburg/San Andres (+2350-2800*) 4. Actidize and fracture treat the San Andres (+2650-2800*) 5. Actidize and fracture treat the Grayburg (+ 2350-2650*) 6. Return well to production. Subsurface Safety Valve: Manu. and Type Senior Engineering SIGNED TITLE DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 1. Clean out to TD 2. Actidize and fracture treat the San Andres (+2350-2800*) 5. Actidize and fracture treat the Grayburg (+ 2350-2650*) 6. Return well to production. Subsurface Safety Valve: Manu. and Type TITLE DESCRIBE PROPOSED OR DRIVE (All Subsurface Safety Valve: Manu. and Type TITLE DESCRIBE PROPOSED OR DRIVE (All Subsurface Safety Valve: Manu. and Type Charles Repeated Andrea (All Subsurface Safety Valve: Manu. and Type Charles Repeated Andrea (All Subsurface Safety Valve: Manu. and Type DATE (All Subsurface Safety Valve: Manu. and Type) Charles Repeated Andrea (All Subsurface Safety Valve: Manu. and Type) Charles Repeated Andrea (All Subsurface Safety Valve: Manu. and Type) Charles Repeated Andrea (All Subsurface Safety Valve: Manu. and Type) Charles Repeated Andrea (All Subsurface Safety Valve: Manu.		15. ELEVATIONS (SHOW	DF, KDB, AND WD)
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING WILTIPLE COMPLETE CHANGE ZONES ABANDON* (other) add perforations and additional pay 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work? 1. Clean out to TD 2. Acidize and fracture treat the San Andres open hole (+2800-3200') 3. Perforated selected Grayburg/San Andres (+2350-2800') 4. Acidize and fracture treat the San Andres (+2650-2800') 5. Acidize and fracture treat the Grayburg (+ 2350-2650') 6. Return well to production. Subsurface Safety Valve: Manu. and Type Set @ Ft. 18. I hereby senify that the foregoing is true and correct Senior Engineering SIGNED TITLE DATE ALASH TITLE DATE ALASH TITLE DATE ALASH TITLE DATE ALASH DATE ALASH PAGE SAFE OF TESTING TESTING TO THE SAFE OF THE SA	REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	3303 😘 🗥	
SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) add perforations and additional pay 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and rure vertical depths for all markers and zones pertinent to this work.)* 1. Clean out to TD 2. Acidize and fracture treat the San Andres open hole (+2800-3200') 3. Perforated selected Grayburg/San Andres (+2650-2800') 4. Acidize and fracture treat the San Andres (+2650-2800') 5. Acidize and fracture treat the Grayburg (+ 2350-2650') 6. Return well to production. Subsurface Safety Valve: Manu. and Type Senior Engineering Signed TitleSpecialist DATE 3-27-84 Appenied By Total Additional pay DATE A-27-84	TEST WATER SHUT-OFF	•	
REPAIR WELL PULL OR ALTER CASING			
MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) add perforations and additional pay 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 1. Clean out to TD 2. Acidize and fracture treat the San Andres open hole (+2800-3200') 3. Perforated selected Grayburg/San Andres (+ 2350-2800') 4. Acidize and fracture treat the San Andres (+2650-2800') 5. Acidize and fracture treat the Grayburg (+ 2350-2650') 6. Return well to production. Subsurface Safety Valve: Manu. and Type Set @ Ft. 18. I hereby settify that the foregoing is true and correct Senior Engineering SIGNED J.	REPAIR WELL		
CHANGE ZONES ABANDON* (other) add perforations and additional pay 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 1. Clean out to TD 2. Acidize and fracture treat the San Andres open hole (+2800-3200') 3. Perforated selected Grayburg/San Andres (+2350-2800') 4. Acidize and fracture treat the San Andres (+2650-2800') 5. Acidize and fracture treat the Grayburg (+ 2350-2650') 6. Return well to production. Subsurface Safety Valve: Manu. and Type Set @ Ft. 18. I hereby certify that the foregoing is true and correct Senior Engineering SIGNED TITLESpecialist DATE 3-27-84 THESPECIAL OF THE STATE	-	change on rolling-3	
ABANDON* (other) add perforations and additional pay 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 1. Clean out to TD 2. Acidize and fracture treat the San Andres open hole (+2800-3200¹) 3. Perforated selected Grayburg/San Andres (+2350-2800¹) 4. Acidize and fracture treat the San Andres (+2650-2800¹) 5. Acidize and fracture treat the Grayburg (+ 2350-2650¹) 6. Return well to production. Subsurface Safety Valve: Manu. and Type Senior Engineering Signify Title Special ist Ghis space for Federal or State office use) Appendix Ft. Appendix Ft			•
Title Separation Separati		7	
including estimated date of starting any proposed work. If well is directionally diffuely give substitute to the measured and true vertical depths for all markers and zones pertinent to this work.) 1. Clean out to TD 2. Acidize and fracture treat the San Andres open hole (±2800-3200') 3. Perforated selected Grayburg/San Andres (±2350-2800') 4. Acidize and fracture treat the San Andres (±2650-2800') 5. Acidize and fracture treat the Grayburg (± 2350-2650') 6. Return well to production. Set @	(other) add perforations and additional pay	•	
3. Perforated selected Grayburg/San Andres (+ 2350-2800') 4. Acidize and fracture treat the San Andres (+2650-2800') 5. Acidize and fracture treat the Grayburg (+ 2350-2650') 6. Return well to production. Subsurface Safety Valve: Manu. and Type	including estimated date of starting any proposed work. It well is to measured and true vertical depths for all markers and zones pertine 1. Clean out to TD	nt to this work.)*	
4. Acidize and fracture treat the San Andres (+2650-2800') 5. Acidize and fracture treat the Grayburg (+ 2350-2650') 6. Return well to production. Subsurface Safety Valve: Manu. and Type	2. Acidize and fracture treat the San Andres of	en hole (+2800-3200)')
Subsurface Safety Valve: Manu. and Type Set @ Ft. 18. I hereby certify that the foregoing is true and correct Senior Engineering SIGNED TITLE Specialist This space for Federal or State office use) APPROVED BY TITLE T. DATE GALLET TITLE T. DATE GALLET DATE GALLET DATE GALLET TITLE T. DATE GALLET DATE GALLET TITLE T. DATE GALLET TITLE T. DATE GALLET DATE GALLET DATE GALLET TITLE T. DATE GALLET DATE GALLET	3. Perforated selected Grayburg/San Andres (+ 3	2350-2800')	
Subsurface Safety Valve: Manu. and Type	4. Acidize and fracture treat the San Andres (F2650-2800')	
Subsurface Safety Valve: Manu. and Type	5. Acidize and fracture treat the Grayburg (+ 2	2350-2650')	
18. I hereby certify that the foregoing is true and correct Senior Engineering TITLESpecialist This space for Federal or State office use) APPROVED BY OF TITLE T. DATE 6/6/54	6. Return well to production.		
18. I hereby certify that the foregoing is true and correct Senior Engineering TITLESpecialist This space for Federal or State office use) APPROVED BY OF TITLE T. DATE 6/6/54			
18. I hereby certify that the foregoing is true and correct Senior Engineering TITLESpecialist This space for Federal or State office use) APPROVED BY OF TITLE T. DATE 6/6/54		* *** * •	
18. I hereby certify that the foregoing is true and correct Senior Engineering TITLESpecialist This space for Federal or State office use) APPROVED BY 11 Detacks TITLE 1. DATE 6/6/54			en e
18. I hereby certify that the foregoing is true and correct Senior Engineering TITLESpecialist This space for Federal or State office use) APPROVED BY 11 Detacks TITLE 1. DATE 6/6/84			
18. I hereby certify that the foregoing is true and correct Senior Engineering TITLESpecialist This space for Federal or State office use) APPROVED BY 11 Detacks TITLE 1. DATE 6/6/54			
SIGNED WITH THE Specialist DATE 3-27-84 THE Specialist DATE 3-27-84 This space for Federal or State office use) APPROVED BY OF State of	Subsurface Safety Valve: Manu. and Type	Set	@ Ft.
APPROVED BY 1 5 Modeller This space for Federal or State office use) APPROVED BY 1 5 Models TITLE 7 F. DATE 6/6/84	John All Selliol Engine	ering	
APPROVED BY DI Getachiba TITLE 7. E. DATE 6/6/84	Wy Ja Moeller		
APPROVED BY DI Solution TITLE T. L. DATE 6/84	This space for Federal or State of	office use)	/a//
	APPROVED BY TO TOUR OF APPROVAL IF ANY:	DATE 6/6/	54