Form 9–331 (May 1963)	DEPAR	UNITE STATE TMENT L. THE GEOLOGICAL SU	ES INTERIO	SUBMIT IN TRIPLIC, (Other instructions of verse side)	5. LEAR	بواجا فتحاج المتحاج	ed. au No. 42-R1424. and berial No.
(Do not		DTICES AND REP openais to drill or to deepe JCATION FOR PERMIT-		CELVED.			E OR TRIBE NAME
UIL WELL X	GAN DOTHE	R	1	NOV 1 4 1979	7. UNIT	AGREEMENT NA	ME
2. NAME OF OPE				HEULUGICAL SURVEY		OR LEASE NAM	A E
General 3. ADDRESS OF	<u>American Oil</u>	. Company of Texa		HESHA, MEN MEXICO	Kee 9. wel	<u>1у В</u> 1 но.	
P. O. BC 4. LOCATION OF See also space At surface	well (Report location of the second s	Hills, New Mexic on clearly and in accordance	co <u>882</u> 5. with any St	ALCONTRACTOR OF LONG	-Gra	LD AND POOL U	kson
198	30' FSL and 1	.980' FEL		O. C. C.		URVEY OR AREA	
				L.L.L. ARTESIA, OFFICE	Sec	26, T-17-	S, R-29-E
14, PERMIT NO.		15. ELEVATIONS (Show	w whether DF, R	T, OR, elc.)	12. COI	INTY OR PARISH	13. STATE
		357	5' GR			Eddy	New Mexico
16.	Check	Appropriate Box To I	ndicate Na	ture of Notice, Report,	or Other Do	ata	
	NOTICE OF 12	TENTION TO:	1	<b>S</b> U	BSEQUENT REP	DET OF:	
TEST WATE	R BHUT-OFF	PULL OR ALTER CASING		WATER SHUT-OFF		REPAIRING V	WELL
FRACTURE T	TREAT	MULTIPLE COMPLETE		FRACTURE TREATMENT	X	ALTERING C	ABING X
RIFOUT OR A	CIDIZE	ABANDON <sup>®</sup>		SHOOTING OR ACIDIZING	, 🗌	ABANDONME	NT*
REPAIR WEL	LL	CHANGE PLANS		(Other) (Note: Report r	osults of multi	pla completion	
(Other)				Completion or Re	completion Rep	port and Log for	rm.)
proposed nent to th	work. If well is dir	rectionally drilled, give sub	all pertinent - surface locatio	details, and give pertinent of and true v	dates, including vertical depths	for all marker	e of starting any s and zones perti-
we CFI 2. Set 3. Pur 4. Rat	ll. Pumped 5 R-2. Laid 1 t Halliburtor mped 100 sach n Free Point.	50 sacks of Clas ' tubing down. n EZSV cement re ks of Class C ce Free Point in	s C cemen tainer @ ment. La dicated @	asing @2140' to o nt containing ½ o 2000' with 2" to aid 2" tubing dow casing stuck @ 12 aid 7" casing dow	of 1% Hal ubing. wn. 388'.	3060' and ad 9 and	l circulated 2/10 of 1%
	5. Shot casing off @ 1380'. Pulled and laid 7" casing down. 6. Ran Sidewall Neutron, Gamma Ray Caliper logs.						
	7. Set cement plug @ 50' inside of 7" and 50' outside of 7".						
9. Cer CFI	<ol> <li>Cemented with 50 sacks of Class H cement containing 10# sand, 5# salt and 1/2 of 1 CFR-2 per sack.</li> </ol>						
sa	nd.						
	sted well. A s. Closed we		was rec	overed, well pum	ped off.	No show	of oil or
18. I hereby cer	tify that the foregol	ng is true and correct				·····	
	Rende CC 1		Ass	t. Field Superin	tendent r	Noven	nber 14, 197

SIGNED COULS A AL AVOID A COM		
(Tingacesfor Federal or State office use)	ACTING DISTRICT LINGINGER	· · ·
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE