

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

RECEIVED

5. Lease Designation and Serial No.

LC028784C

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Burch Keely Unit

8. Well Name and No.

Burch Keely Unit #207

9. API Well No.

30-015-03137

10. Field and Pool, or Exploratory Area

Grbg. Jackson SRQ Grbg. SA

11. County or Parish, State

Eddy Co., N.M.

Type of Well

Oil Well  Gas Well  Other

Name of Operator

Marbob Energy Corporation

Address and Telephone No.

P.O. Drawer 217 Artesia, New Mexico 88210 (505)748-3303

Location of Well (Footage, Sec., T., R., M., or Survey Description)

660FSL 1980FWL, Sec. 26 T-17-S R-29-E Unit N

JAN 26 1995

OIL CON. DIV.

EDDY CO.

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- Notice of Intent
- Subsequent Report
- Final Abandonment Notice

TYPE OF ACTION

- Abandonment
- Recompletion
- Plugging Back
- Casing Repair
- Altering Casing
- Other \_\_\_\_\_
- Change of Plans
- New Construction
- Non-Routine Fracturing
- Water Shut-Off
- Conversion to Injection
- Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 1) Spot 120 Sacks cement plug at 2964 W.O.C. tag cement top at 2187"
- 2) Load hole W/mud
- 3) Perforate 7" casing at 875' base of salt and squeeze W/50 sacks of cement W.O.C. tag top of cement at 755'
- 4) Perforate 7" casing at base of 8 5/8 shoe at 465' and squeeze W/50 sacks of cement and W.O.C. tag cement top at 325'
- 5) Perforate 7" casing at 50' and circulate cement to surface W/35 sacksof cement and set P.A. marker

Work completed 12/12/94

Post ID-2  
2-17-95  
P&A

I hereby certify that the foregoing is true and correct

Signed Raymond Maldonado Title Supervisor Date 12/12/94

(This space for Federal or State office use)

Approved by \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_  
Conditions of approval, if any: \_\_\_\_\_

18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side