(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Lan Gruces
Lease No	028784-C
_	Fools C

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	1	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	1
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING.	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	1	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	1
NOTICE OF INTENTION TO PULL OR ALTER CASING	i	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL.			
		Anheogram's Report of Sandoll	

		wheequeut Re	port of Sandell	23
(INDICATE	E ABOVE BY CHECK MARK NATURI	E OF REPORT, NOTICE,	OR OTHER DATA)	
	Less	Hille, New	icaico Sept. 2	6 , 19 .55 .
Well No. 27-6 is locate	d 990 ft. from [N]	line and 330	ft. from W line of	sec. 26
(½ Sec. and Sec. No.)	(Twp.) (Range)	Mei (Mei	idian	
(Field)	(County or Subdiv		(State or Territory)	
The elevation of the derrick f	loor above sea level is	5799 ft.	81 - 17 - 18 18 - 18 - 18 - 18 - 18 - 18 - 18 -	State of the state
	DETAILS O	F WORK		
of fluck 2000 pei/ 27 min. Avg. inj. eil 628 bble. Pe	tus: Loaded hole to deg. API refixed of ed with 66 bble, or g, dropping to 1600 . rate 17 SM with reheard oil 218 bbl	rith 96 80. ril & 150 bb] rudo. Hex. 1 9 paig on ote 2 PIV pume	Breke dom with A. erude contain Mj. press. 2600 Mping pump. 201 A 2 AP mana by	hl BO (crude) ning 23,000 prigs at end hal into time
PESULTS OF TRATERITY 9-3 Ram 2" SUE to 327 9-4 Sumbod 122 bblo. 9-1 S.d. Armbak (Sig. 193.) No.	ell, 19 bbls. web life.dhlap.Shilbhillegi	y the Cological Surv	ey before operations may be	
Company Carral America	M OIL COMPANY OF !	rationed on I	∌€o ≲	
Address P. 0. Box 116				
LOGO ELLLS, MIN		ву К	Mad	
LOSO SILLS, SE		By	i. Board	

General American Oil Co. of Toxas

Page 2

Subsequent Report of Sandeil, Keely C-27

Sept. 26, 1955

RESULTS OF TREATMENT (Cont'd):

9-6 Swab & fle 194 BO, 58 bbls. water. 9-7 Swab & fle 139 BO, 31 bbls. water. HET 130 BO.

SUBSEQUENT TESTS:

9-22 Flowed 39 80 & 7 bbls. water in 12 hrs.

Subsequent Report of Sandoil, Keely 0-27

Sept. 26, 1955

RESULTS OF TREATMENT (Cont'd):

9-6 Swab & 110 194 30, 53 bble. water. 9-7 Swab & 110 139 80, 31 bble. water. Wat 130 80.

SUBSEQUENT TESTS:

9-27 Flowed 39 BO & 7 bbls. water in 12 lars.