

(SUBMIT IN TRIPLICATE)

Land Office Las CrucesLease No. 028480 (b)Unit Group BUNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED

DEC 3 1952

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Loco Hills, New Mexico May 28, 19 59Well No. 8 is located 330 ft. from S line and 2310 ft. from W line of sec. 29SE SE SW Sec. 29 17-S 29-E N.M.P.M.
(¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)Grayburg-Jackson Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)The elevation of the derrick floor above sea level is 3593 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

WE PLUGGED AND ABANDONED THE ABOVE WELL AS FOLLOWS:

Filled hole with mud from T.D. 2708' back to 2400';

Set cement plug of 15 sacks from 2400' to 2350';

Filled hole with mud from 2400' to 733';

Set cement plug of 10 sacks from 733' to 700';

Filled hole with mud to surface and erected regulation marker.

NOTE: The above program is essentially the same as outlined in telephone conversation between R. F. Miller and Artesia U.S.G.S. office.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company GENERAL AMERICAN OIL COMPANY OF TEXASAddress P. O. BOX 416LOCO HILLS, NEW MEXICOBy R. J. HeardTitle District Superintendent