

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	
LAND OFFICE	
OPERATOR	☒

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

NOV 15 '88

O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1

3a. Indicate Type of Lease	
State ☒	Fee ☐
3. State Oil & Gas Lease No.	
E-4201	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER		7. Unit Agreement Name
2. Name of Operator ARCO Oil and Gas Company		8. Farm or Lease Name Empire Abo Unit "B"
3. Address of Operator P.O. Box 1610, Midland, Texas 79702		9. Well No. 46
4. Location of Well UNIT LETTER <u>F</u> <u>2310</u> FEET FROM THE <u>North</u> LINE AND <u>1254</u> FEET FROM THE <u>West</u> LINE, SECTION <u>30</u> TOWNSHIP <u>17S</u> RANGE <u>29E</u> NMPM.		10. Field and Pool, or Wildcat Empire Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3634 GR		12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-03-88 RU PU. POH w/CA. Tag PBD 6294' w/bit. Set pkr at 6207'. Press test csg to 500#. Swb'd Abo perfs 6273-6284'.
10-06-88 Set RBP at 6265'. Perf Abo f/6240-6244'. Set pkr at 6145' & swab test.
10-10-88 Re-set RBP at 6235'. Perf Abo f/6216-6222'. Set pkr at 6108' and swab test.
10-12-88 WL set CIBP at 6198'. Perf Abo f/6084-90' & 6108-6114'. Set pkr at 6028'. Found hole in casing at surf. Repaired csg. Set pkr at 6024'. Acdz'd w/1500 gals. Swabbed test.
10-20-88 Dumped 35' cmt on CIBP at 6198'. WL set CIBP at 6050' & dumped 35' cmt on top.

Well temporarily abandoned.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Kenneth Gosnell TITLE Engr. Tech. 915-688-5672 DATE 11-10-88

Original Signed By
Mike Williams

APPROVED BY _____ DATE NOV 10 1988

CONDITIONS OF APPROVAL, IF ANY: