Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

OCT - 5 1992

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

Expires: March 31, 1993

5. Lease Designation and Serial No.

SUBMIT IN TRIPLICATE 1. Type of Well X Well Gas Other	1. Type of Well X Well		7. If Unit or CA, Agreement Designation Artesia Seven Waterflood 8. Well Name and No. Leonard Federal #9
1. Type of Well Soli Gas Other			
2050' FSL & 2310' FEL of Section 30 T-17S, R-29-E CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Abandonment Change of Plans			
TYPE OF SUBMISSION TYPE OF ACTION Abandonment Change of Plans	2050' FSL & 2310' FEL of Section 30		Artesia Queen Grayburg SA 11. County or Parish, State Eddy Co., New Mexico
Notice of Intent Abandonment Change of Plans	12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA
} · · · · · · · · · · · · · · · · · · ·	TYPE OF SUBMISSION	TYPE OF ACTION	
Subsequent Report Plugging Back Casing Repair Final Abandonment Notice Plugging Back Non-Routine Fracturing Water Shut-Off Altering Casing Conversion to Injection	Subsequent Report	Recompletion Plugging Back Casing Repair	New Construction Non-Routine Fracturing Water Shut-Off
	give subsurface locations and measured and true vertice	pertinent details, and give pertinent dates, including estimated date of starti	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
14. I hereby certify that the foregoing is true and correct	14. I hereby certify that the foregoing is true and correct		
Signed		Tide <u>Operations Manager</u>	Date10-1-92
(This space for Federal or State office use) Approved by Title Date Conditions of approval, if any:	Approved by	Title	Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements

or representations as to any matter within its jurisdiction.

RECOMPLETION PROCEDURE

LEONARD FEDERAL #9

- 1. MIRU. POOH WITH RODS AND PUMP.
- 2. ND WH, NU BOP.
- 3. TOOH WITH 2-3/8" TUBING.
- 4. TIH WITH 3-7/8" BIT AND 4-1/2" CASING SCRAPER ON 2-7/8" WORKSTRING. CLEAN OUT TO PBTD AT 2698'. REVERSE HOLE CLEAN AND POOH.
- 5. DUMP SAND TO PLUG BACK TO 2500'.
- 6. PERFORATE: 2425-27', 2418-20', 2364-66', 2326-28', 2309-12', 2303-05', 2468-70' (ALL 2 SPF, 180 PHASING, 30 NEW HOLES).
- 7. RIH WITH PIP TOOL. RU DOWELL. TEST TUBING AND CASING. BREAKDOWN ALL PERFS WITH 2% KCL AND ACIDIZE WITH 15% HCL. POOH TO 2200' AND SWAB BACK LOAD. RU FOR FORCED CLOSURE.
- 8. FRAC WELL WITH 38000 GALS. BORATE CROSSLINKED GUAR AND 197,000# 12/20 SAND PER ATTACHED SCHEDULE. ANTICIPATED RATE 25 BPM @ 3000 PSI. FORCE CLOSE WELL.
- 9. RELEASE PACKER AND POOH. RIH WITH NOTCHED COLLAR AND CLEAN OUT SAND TO PBTD. POOH, LD WORKSTRING.
- 10. RIH WITH 2-3/8" TUBING. ND BOP, NU WH. RIH WITH PROGRESIVE CAVITY PUMP AND RODS.
- 11. RD AND MOL. RWTP.