

30-015-03196

J-33-175-290

Webb Oil Co.

C-State #2

Top

T. Salt - 260'

B. Salt - 675'

* Perforate 4 1/2" csg to 30'. Circulate cement to surface.

* Perforate 4 1/2" csg to 410'. Squeeze 100' cement Plug
Inside & Outside 4 1/2" csg. TAG

* Perforate 4 1/2" csg to 725'. Squeeze 100' cement Plug
Inside & Outside 4 1/2" csg. TAG

* Circulate brine gel.

* Spot 255x cement Plug 2800' - 2700'. TAG

± Perf.s. 2876' - 2890'.

4 1/2" csg

3000'

w/350 x